



MOBILE BAREFOOT KARAVAN TEAMS

During the month of April, Heritage Foundation's Mobile Barefoot Karavan Team continues its relentless efforts to Build Back Safer with Vernacular Methodologies, with DRR Compliant Sustainable Construction for the community in Village *Obayo Mir*, District *Tando Allayar*. Housing units were retrofitted with Karavan Roofs while damages to walls were rectified using bamboo infill and mud brick. Awareness Campaigns were held for the community to explain the importance of disaster resilient measures, such as the construction of a toe at the base of walls, the use of lime in mortars and plasters and strong resilient roofs. With the completion of the units in the village, community members have learnt methods of Disaster Risk Reduction gaining experience that will create resilient communities.

The community attended a training workshop at the beginning of the programme to understand the correct method of tying the Karavan 6-bamboo joists to the ring beam, anchoring of walls to both base and roof. Once bases were strengthened with toes and platforms, walls repaired with infill, and Karavan Roofs secured, community members were urged to test their new and improved housing unit, by collecting 15 people of the community on the roof. Communal buildings are now required to ensure that people have additional space for safety during times of the monsoon. We are now looking for support for the construction of a small dispensary and a women's centre which would be completed at a cost of Rs. 150,000.

The Heritage Foundation would like to extend its thanks to the anonymous donor, Mr. BK, for the completion of 52 Units in the Village of *Obayo Mir*. Please find list of beneficiaries below.



Photographs:
AFTER
1. Havi and his family,
2. Dharmi and her children,
3. Dharmu and her son,
4. Rano
BEFORE
5. Havi's House
6. Dharmu
7. Rano




S.No.	Name	NIC No.
1	Rano	41307-1397395-7
2	Jeevan Din	41701-0583365-9
3	Ramji	41307-1419559-9
4	Jagsee	41307-3521002-7
5	Amarshi	41701-0618065-5
6	Narayan	41307-0928163-3
7	Shavo	41307-7829734-7
8	Tursi	41307-9925282-5
9	Narayan Tursi	41701-0681028-9
10	Aambho	41307-6867971-3
11	Dharmi	41307-7709422-6
12	Kewal	41701-0618289-1
13	Walo	41307-1436140-9
14	Amarshi Ramji	41701-0583220-1
15	Randshi	41701-0583158-9
16	Pirbhu	454-74203346-4
17	Ramu	41307-5805534-7
18	Tursi Ramu	41701-0583161-1
19	Dharmu	41307-2850927-9
20	Manu	41701-0618900-9
21	Dayalo	41307-5689153-9
22	Fakeera	357-5017437-1
23	Pelaj	---
24	Popat	---
25	Rajoo	41307-0573152-5
26	Gyaan	---

S.No.	Name	NIC No.
27	Mavo	41307-3266437-5
28	Ramji Mavo	41307-0625191-9
29	Havi	41307-1682256-8
30	Raiero	41307-4222685-5
31	Hashoo	41701-0618066-7
32	Bhura	---
33	Harchan	41103-0236399-1
34	Kambo	41701-0618030-5
35	Shamdri	41701-0616719-0
36	Kanji	41307-4898244-9
37	Naaran	41701-0599708-5
38	Dawoo	41701-0600919-1
39	Viyo	41701-0600452-3
40	Kheemun	41701-0585718-9
41	Kanu	---
42	Hari	41307-9159977-5
43	Popat Nilo	41307-8440389-5
44	Ramji Mithu	41701-0618063-9
45	Mithu	41307-4696489-1
46	Meeran	---
47	Ramu	---
48	Kanji	---
49	Ganga Ram	---
50	Dayaloo	---
51	Aarji	41307-7966735-9
52	Nanji	41307-7357258-7




PLAN




پلان

PLAN




پلان

ELEVATION



ایلیویشن

ELEVATION



ایلیویشن

SITE OBSERVATIONS:

Walls: Back wall has collapsed completely, Cracks on wall corners.
Roof: Damaged Bamboo roof supported by wooden logs