



GOVERNMENT OF SINDH //35_ CULTURE, TOURISM & ANTIQUITIES DEPARTMENT

NOTIFICATION

No. OSD/CHC/MRQ-01-49/2017: In exercise of the powers conferred by Sub-Section (1) of Section-6 of the Sindh Cultural Heritage (Preservation) Act, 1994, and on the recommendations of Advisory Committee on Sindh Cultural Heritage, the Culture, Tourism & Antiquities Department, Government of Sindh is pleased to declare the premises/buildings described below to be Protected Heritage within the meaning of the said Act.

(MARKET QUARTER KARACHI)

| S.NO. | NAME OF BUILDING | PLOT # | ADDRESS | REASON FOR ENLISTMENT AS HERITAGE |
|-------|-----------------------------|--------------------|---|---|
| 1. | Tayab Building | MR-1/4, | Old Kund Street Now Muhammad Mosa Street Murad Khan Road Khorai Garden Market Area | Architectural Value |
| 2. | Ghousia Building | MR-1/6, | Murad Khan Road, Kunda Street | Architectural Value |
| 3. | Aijaz Building | MR-1/22, | Murad Khan Road. Kunda Street: | Architectural Value |
| 4. | Max Denso Hall & Library | MR-1/ 152, | M. A. Jinnah (Bunder) Road, Marriott Road, Karachi | Architectural Value |
| 5. | Marriam Building | MR-1/ 157, | Shahrah-e-Altaf Husain (Napier Road), Kucchi Wada Lane. 1, Karachi | Architectural Value |
| 6. | Hatim Bhai Building | MR-1/ 159, | Shahrah-e-Altaf Husain (Napier Road), Kucchi Wada Lane. 1, Karachi | Architectural Value |
| 7. | Alvi Chambers | MR-1/ 162, 163, | Shahrah-e-Altaf Husain (Napier Road), Karachi | Architectural Value |
| 8. | Hamid Market | MR-1/ 149, | M. A. Jinnah (Bunder) Road, Marriott Road, Karachi | Architectural Value |
| 9. | B. K. Trust Building | MR-1/ 150, | M. A. Jinnah (Bunder) Road, Marriott Road, Karachi | Architectural Value |
| 10. | Quetta Wala Building | MR-1/ 129, | Marriott Road, Kucchi Wada Lane. 2, Karachi | Architectural Value |
| 11. | Kara Mora Building | MR-1/69, | Murad Khan Road, Karachi | Architectural Value |
| 12. | Habib Bank | MR-1/ 66/ 1, | Murad Khan Road, Karachi | Architectural Value |

| 1 | | | | (64 |
|-----|---|--------------------|---|---------------------|
| 13. | Nagaria Building (Building On The Left) | MR-1/ 90, | Kucchi Wada Lane No. 3, Karachi | Architectural Value |
| 14. | Building On The Right of Nagaria Building | MR-1/ 91, | Kucchi Wada Lane No. 3, Karachi | Architectural Value |
| 15. | Aziz Mansion | MR-1/64, | Murad Khan Road, Katchi Galli, Karachi | Architectural Value |
| 16. | Samaj Trust | MR-1/83, | Kucchi Wada Lane. 1, Jodia Bazar, off Daryalal Street, Karachi | Architectural Value |
| 17. | Faiz-e-Alvi Trust Building, 1 | MR-1/50, | Daryalal Street, Murad Khan Road, Karachi | Architectural Value |
| 18. | Shakoor Manzil | MR-1/ 23 | Kunda Street, off Murad Khan Road, Karachi | Architectural Value |
| 19. | Badri Mahal | MR-1/ 24, | Kunda Street, off Murad Khan Road, Karachi | Architectural Value |
| 20. | Hilal Chamber | MR-1/ 25/ 1, 2, | Kunda Street, off Murad Khan Road, Karachi | Architectural Value |
| 21. | Karachi Kirana Building | MR-1/28, | Ram Bharti Street, Karachi | Architectural Value |
| 22. | Taj Chamber | MR-1/ 48, | Khori Road, Karachi | Architectural Value |
| 23. | Rang Wala Building | MR-1/ 45, | Khori Road, Murad Khan Road, Karachi | Architectural Value |
| 24. | Mohsin Ali Building | MR-1/ 142/ 1, | M. A. Jinnah (Bunder) Road, Karachi | Architectural Value |
| 25. | Badri Masjid (Bohri Mosque) | MR-2/ 36, | Ram Bharti Street, Marriott Road, Karachi | Architectural Value |
| 26. | Chaudhry Chambers (Ammama Building) | MR-2/ 14, | Marriott Road, Ram Bharti Street, Karachi | Architectural Value |
| 27. | Rehan Building | MR-2/ 13, | Ram Bharti Street, Marriott Road, Fakhr Matri (Newnham) Road, Karachi | Architectural Value |
| 28. | Lotia Manzil | MR-2/6, | Marriott Road, Fakhr Matri (Newnham) Road, Karachi | Architectural Value |
| 29. | Shams Building | MR-2/ 4, | Marriott Road, Fakhr Matri (Newnham) Road, Karachi | Architectural Value |
| 30. | Azeem-Ud-Din Building | MR-7/ 63, | Ram Bharti Street, Adamjee Dawood Pota (Rampart) Road, Karachi | Architectural Value |

| 31. | Shafai Matab(Seth Shewaram RamrakhiamalCharitable Deshi Dispensary) | MR-3/ 16, | Market Road, karachi | Architectural Value |
|-----|--|-----------|---|---------------------|
| 32. | Dada Chambers | MR-3/7, | Adamjee Dawood Pota (Rampart) Road, Market Road, Karachi | Architectural Value |
| 33. | Fazal Chamber/ G.B Saeed Company | MR-1/72 | Marriot road, Murad khan road, Kucchi wada Lane No.3 Market | Architectural Value |

In accordance with Section 6(2) of the Sindh Cultural Heritage (Preservation) Act, 1994, any objection to the issuance of the notification should be addressed to the Government i.e. Culture, Tourism & Antiquities Department, Government of Sindh, within one month from the date of its publication.

Any intentional act to destroy, alter, deface and imperil the Protected Heritage or to build on or near the sites will be unlawful, and punishable under section 18 of the Sindh Cultural Heritage (Preservation) Act, 1994.

-GHULAM AKBAR LAGHARI-

No.OSD/CHC/MRQ-01-49/2017

Secretary to Govt. of Sindh Karachi dated the 23rd January, 2018

A copy is forwarded for information and necessary action to:-

- The Chief Secretary, Sindh / Chairman Advisory Committee on Sindh Cultural Heritage.
 - 2. The Chairman, Planning & Development Board, Govt. of Sindh.
 - The Chairman, Technical Committee on Sindh Cultural Heritage.
 - 4. The Administrative Secretaries (All), Government of Sindh.
- The Senior Member, Board of Revenue, Government of Sindh, with request not to partition above heritage properties, without prior approval of Advisory Committee.
- The Commissioner, Karachi.
- The Director General, Sindh Building Control Authority.
- The Director General (Antiquities & Archaeology), CT&AD, Government of Sindh.
- The Director (Heritage), CT&AD, Government of Sindh
- 20. All Members of Advisory / Technical Committee on Sindh Cultural Heritage.
- 11. The Administrator (SZ), Evacuee Trust Properties, Karachi.
- 12. The Chief Executive Officer, Cantonment Board, Karachi.
- 73. The Deputy Commissioner-South, Karachi.
- 14. The Superintendent, Sindh Government Printing Press, Government of Sindh, He is requested to supply 50 copies of the Sindh Government Gazette to this department for official
- 15. PS to Minister of Culture, Tourism & Antiquities Department Government of Sindh, Karachi.
 - 16. The Owner / Occupant.

17. Notification File.

(HERITAGE)

For Secretary to Govt. of Sindh





GOVERNMENT OF SINDH CULTURE, TOURISM & ANTIQUITIES DEPARTMENT

ADDENDUM - 1

No. OSD/CHC/MRQ-01-49/2017: In continuation of this Department's Notification of even number dated 18th December, 2017 and in exercise of the powers conferred by Sub-Section (1) of Section-6 of the Sindh Cultural Heritage (Preservation) Act, 1994, and on the recommendations of Advisory Committee on Sindh Cultural Heritage, the Culture, Tourism & Antiquities Department, Government of Sindh is pleased to declare the premises/buildings described below to be Protected Heritage within the meaning of the said Act.

(MARKET QUARTER KARACHI)

| S.NO. | NAME OF BUILDING | PLOT # | ADDRESS | REASON OF ENLISTMENT A |
|-------|-------------------------------------|-----------------|---|--|
| √34. | Khadija Bai Building | MD 1 / 22 | | HERITAGE |
| 35. | Haris Bhai Building | MR-1/32, | Rambharti Road; | Architectural Valu |
| 36. | Menghraj Building | MR-1/34, | Rambharti Road; | Architectural Value |
| √37. | Jamal Mansion | MR-1/39, | Marriot Road: | Architectural Value |
| √38. | Mandvi Wala | MR-1/40, | Marriot Road; | Architectural Value |
| 39. | | MR-1/41, | Marriot Road: | Architectural Value |
| | Faiz-e-Alavi Trust Building No.1 | MR-1/50, | Daryalal Street, Murad Khan Road | Architectural Value |
| 40. | Feroz Chambers | MR-1/ 46/ 1, | Khori Road: | Architectural Value |
| 41. | Amjad Building | MR-1/53, | Murad Khan Road: | A 111 |
| 42. | Haji Dawood & Sons | MR-1/55, | Kucchi Wada Lane No. 3, Kucchi | Architectural Value Architectural Value |
| 43. | Unknown | MR-I/ 61, | Gali; Daryalal Street, Kucchi Wada No. 3; | Architectural Value |
| 44. | Abbas Manzil | MR-1/ 65/1, | Murad Khan Road, Kucchi Wada Lane No. 3; | Architectural Value |
| 46. | Hyderi Manzil | MR-1/ 65/ 2, | Murad Khan Road, Kucchi Wada Lane No. 3; | Architectural Value |
| 47. | Rahim Manzil | MR-1/ 65/3, | Murad Khan Road, Kucchi Wada Lane No. 3; | Architectural Value |
| 48. | Unknown | MR-1/ 66/ 1, | Murad Khan Road, Kucchi Wada Lane No. 3; | Architectural Value |
| 49. | Saleem Paracha Building | MR-1/ 66/ 2, | Murad Khan Road. Kucchi Wada Lane No. 3; | Architectural Value |
| 50. | Hafiz Muhammad Yousaf Market | MR-1/ 66/3. | Murad Khan Road. Kucchi Wada Lane No. 3; | Architectural Value |
| | Unknown | MR-1/74, | Kacchi Wada Lane No. 3: | Architectural Value |

1 | Page (Heritage Buildings Notification, Market Quarter)



C



| | | 1 |
|---|----|----|
| 1 | 1 | 7) |
| | 6. | セノ |
| / | | - |

| | 1/ | | | (67) |
|--------------|-----------------------|---------------|---|--|
| | Jafri Manzil | MR-1/76 | | |
| 1 | // | | Julia Street, Ruccin Wada | Architectural Value |
| 1/5 | 2. Haji Iftikhar Udin | MR-1/78 | Lane No. 3; | |
| 4 | Building | | Kucchi Wada Lane No. 3: | Architectural Value |
| | Farzana Mansion | MR-1/79 | , Kucchi Wada Lane No. 3; | 4 10 |
| 5. | / Countries | MR-1/94 | Kacchi Wada Lane No. 3; | Architectural Value |
| 55 | Building | | Tracent Wada Lane No. 3; | Architectural Value |
| 1 | Tahir Bhai Palace | MR-1/ | Marriot Road, Kacchi Wada | Architectural Value |
| 56 | Innois Manai | 101/2, | Lane No. 3; | Ancintectural value |
| V- | Junejo Mansion | MR-1/ | Kacchi Wada Lane No. 2; | Architectural Value |
| 57 | Unknown | 105. | | |
| | CHRIOWII | MR-1/ | Kacchi Wada Lane No. 2, Kucchi | Architectural Value |
| 58 | Sultan Trading & Co. | 115, | Galli; | , unde |
| 1 | Trading & Co. | | Kacchi Wada Lane No. 2; | Architectural Value |
| 59 | Allah Wala Building | 118, | | |
| | dia banding | MR-1/ 130, | Marriot Road. Kacchi Wada | Architectural Value |
| 60, | Unknown | MR-1/ | Lane No. 1; | Secret Accessors (1979) |
| 1 | / | 131, | Kacchi Wada Lane No. 1; | Architectural Value |
| 61. | . Evacue Trust | MR-1/ | Variation | |
| · 1/200 | Building | 136, | Kacchi Wada Lane No. 1; | Architectural Value |
| 62. | Mohsin Habib | MR-1/ | M A linnal (B 1) B | |
| | Building | 144, | M. A. Jinnah (Bunder) Road. | Architectural Value |
| 63 | Fida Hussain Qadir | MR-1/ | Marriot Road; | |
| | Bhai Building | 151, | M. A. Jinnah (Builder) Road, Marriot Road; | Architectural Value |
| 64 | Seth Bhai Building | MR-I/ | Daryalal Street; | |
| | | 154, | Dai yalai Street, | Architectural Value |
| 65. | Razaque Chamber | MR-I/ 158, | Shahrah-e-Altaf Hussain (Naiper | A 114 . 177. |
| - | | | Road), Kacchi Wada Lane No. 1; | Architectural Value |
| 66. | S. Nawab Brothers | MR-1/ | Sharah-e-Altaf Hussain (Napier | Architecture 177.1 |
| (7) | | 160, | Road), Kacchi Wada Lane No. 1; | Architectural Value |
| 67. | Madina Centre | MR-1/ | Shahrah-e-Altaf Husain (Napier | Architectural Value |
| 16 | Point VV | 167, | Road), Kacchi Wada Lane No. 1; | - menticetatai value |
| 68. | Faizan-e-Hussain | MR-2/12, | Marriot Road, Fakhr Matri | Architectural Value |
| . /69. | Building | 3.45 | (Newnaham) Road; | value |
| V 05. | Bhai Jan Building | MR-2/23, | Abdul Majid Sindhi Road, | Architectural Value |
| , 70. | Karachi Muslim | MDO/S | Marriot Road; | - Fund |
| V. | Restaurant | MR-2/31, | Abdul Majid Sindhi Road, | Architectural Value |
| 11. | Lakshmi Building | MD 2 / 22 | Daulat Ram Road; | |
| 7 | Laksimi bunding | MR-2/32, | M. A. Jinnah (Bunder) Road, | Architectural Value |
| /72. | Zamindar Market | MD 2/25 | Chagla Road: | 2 |
| / | | MR-2/35, | M. A. Jinnah (Bunder) Road, | Architectural Value |
| 73. | Unknown | MR 27 47 | Ram Bharti Street: | to the second se |
| / | , , | MR-2/47, | Marriot Road, off Murad Khan | Architectural Value |
| 74. | Lotia Building | MR-2/49, | Road; | |
| | | 17111-2/ 49, | M. A. Jinnah (Bunder) Road, | Architectural Value |
| 15. | Unknown | MR-3/3, | Murad Khan Road | 4-94 |
| | | | Adamji Dawood Pota (Rampart). | Architectural Value |
| | | | Road; | |

2 | Page (Heritage Buildings Notification, Market Quarter)

6



| - | 1 | | | (68) |
|-------------|--|------------------|--|---------------------|
| 1 | Unknown | MR-3/4, | Adamji Dawood Pota (Rampart) Road; | Architectural Value |
| 177N | Halana Mansion | MR-4/ 10, | Ali Akbar Street; | Architectural Value |
| 78. | Noor Bhai Mansion | MR-4/ 28, | -i in Tinoui Outcom | Architectural Value |
| 79.v | Mansoor Building | MR-4/37, | Moosa Lane, Zakariya Lane; | Architectural Value |
| 80 | Haji Yousuf Manzil | MR-4/39, | Zakariya Lane; | Architectural Value |
| 81. | Ali Hussain, Abdul Hussain Building | MR-5/ 10, | Daryalal Street; | Architectural Value |
| V 82. | Bombay House | MR-5/ 45, | Khooshal Lane, All Akbar Street; | Architectural Value |
| 83. | Jholay Lal Temple | MR-5/ 97, | Thakur Lane, Siraisi Street; | Architectural Value |
| /84. | Malik Bhai Building | MR-5/ 106, | Siraisi Sheet, Virji Street; | Architectural Value |
| 85 . | Unknown | MR-5/ 110/ 1, | Siraisi Street, off Daryalal Street; | Architectural Value |
| /86. | Unknown | MR-5/ 110/ 2, | Daryaial Street; | Architectural Value |
| 87. | Arafat Chamber | MR-5/ 128, | Zakariya Lane; | Architectural Value |
| 88. | Soneri Bank Building | MR-5/ 139, | Thanai Lane; | Architectural Value |
| 89. | Unknown | MR-5/ 140, | Thanai Lane; | Architectural Value |
| 90. | Unknown | MR-6/1, | Daryalal Street, Virji Street; | Architectural Value |
| 91. | Unknown | MR-6/2, | Virji Street; | Architectural Value |
| 9 2. | Haji Razak Janod Ltd | MR-6/7, | Abdul Rehman Street, Muhammad Feroz Street; | Architectural Value |
| 93. | Abdul Aziz All Muhammad | MR-6/ 11, | Daryalal Street; | Architectural Value |
| 94. | Unknown | MR-6/ 14, | Virji Street, Khund Street; | Architectural Value |
| 95. | Unknown | MR-6/ 20, | Virji Street, Abdul Rehman Street; | Architectural Value |
| 96. | Unknown | MR-6/21, | Virji Street, Abdul Rehman Street; | Architectural Value |
| /97. | Sopariwala Building | MR-6/23, | Abdul Rehman Street, Muhammad Feroz Street; | Architectural Value |
| 98. | Khori Garden (Muslah-ud-din) | MR-1/36, | Rambharti Road, Khori Road; | Architectural Value |
| 99. | Devi Mandir | MR-3/10, | Adamjee Dawood Pota (Rampart) Road, Karachi | Architectural Value |
| 100. | Sultan Mansion | MR-4/30, | Adamjee Dawood Pota (Rampart) Road, Market Road, Karachi | Architectural Value |
| 101. | Bastaki Manzil | MR-6/ 22, | Virji Street, Abdul Rehman Street, Karachi | Architectural Value |
| 102. | Ram Padhomal Building | MR-6/ 17, | Zakariya Lane, Abdul Rehman Street, Karachi | Architectural Value |
| 103. | Unknown | MR-6/30, | Daryalal Street, Karachi | Architectural Value |
| 104. | Chaudhray Piracha Chambers | MR-4/ 13, | Zakariya Lane, Abdul Rehman | Architectural Value |

3 | Page (Heritage Buildings Notification, Market Quarter)

Street, Karachi

Chambers



| | 69) |
|---------------|-------|
| Architectural | Value |
| Architectural | Value |

| 1065 | Gulzar Manzil Shehla Mansion | MR-5/ 15/ 2, MR-5/ 60, | Old Dispensary Road, Khooshal Lane, Karachi | |
|------|--|------------------------------|--|--|
| 107. | Karachi Kirana Building/ Zubair Manzil | 1/ 28 | Daryalal Street, Karachi Ram Bharti Street | Architectural Value Architectural Value |

In accordance with Section 6(2) of the Sindh Cultural Heritage (Preservation) Act, 1994, any objection to the issuance of the notification should be addressed to the Government i.e. Culture, Tourism & Antiquities Department, Government of Sindh, within one month from the date of its publication.

Any intentional act to destroy, alter, deface and imperil the Protected Heritage or to build on or near the sites will be unlawful, and punishable under section 18 of the Sindh Cultural Heritage (Preservation) Act, 1994.

-GHULAM AKBAR LAGHARI-

No.OSD/CHC/MRQ-01-49/2017 190 A

Secretary to Govt. of Sindh Karachi dated the 08th March, 2018

A copy is forwarded for information and necessary action to:-

- The Chief Secretary, Sindh / Chairman Advisory Committee on Sindh Cultural Heritage.
- The Chairman, Planning & Development Board, Govt. of Sindh.
- The Chairman, Technical Committee on Sindh Cultural Heritage.
- The Administrative Secretaries (All), Government of Sindh.
- The Senior Member, Board of Revenue, Government of Sindh, with request not to partition above heritage properties, without prior approval of Advisory Committee.
- The Commissioner, Karachi.
- The Director General, Sindh Building Control Authority.
- The Director General (Antiquities & Archaeology), CT&AD, Government of Sindh.
- 7. The Director (Heritage), CT&AD, Government of Sindh.
- All Members of Advisory / Technical Committee on Sindh Cultural Heritage.
- 11. The Administrator (SZ), Evacuee Trust Properties, Karachi.
- 12 The Chief Executive Officer, Cantonment Board, Karachi.
- 13. The Deputy Commissioner-South, Karachi.
- 14. The Superintendent, Sindh Government Printing Press, Government of Sindh, for publication in the next issue of Sindh Government Gazette, and requested to supply 50 copies of the Sindh Government Gazette to this department for official use.
- PS to Minister of Culture, Tourism & Antiquities Department Government of Sindh, Karachi.

The Owner / Occupant.

Notification File.

(HEMTAGE)

For Secretary to Govt. of Sindh

M. Faish of

ADDENDUM-2





GOVERNMENT OF SINDH CULTURE, TOURISM & ANTIQUITIES DEPARTMENT

NOTIFICATION

No. OSD/CHC/MRQ-01-49/2017: (Addendum-02) In exercise of the powers conferred by Sub-Section (1) of Section-6 of the Sindh Cultural Heritage (Preservation) Act, 1994, and on the recommendations of Advisory Committee on Sindh Cultural Heritage, the Culture, Tourism & Antiquities Department, Government of Sindh is pleased to declare the premises/buildings described below to be Protected Heritage within the meaning of the said Act.

(MARKET QUARTER KARACHI)

| S.NO. | NAME OF DUM DING | Dr om " | 155556 | |
|-------|------------------|---------|-----------------------------|--|
| S.NO. | NAME OF BUILDING | PLOT # | ADDRESS | REASON FOR |
| | | | | ENLISTMENT AS |
| 100 | | ļ | | HERITAGE |
| 108. | Unknown | MR-1/ | Murad Khan Road; | Architectural Value |
| ~ | | 52, | | |
| 109. | Hafiz Muhammad | MR-1/ | Murad Khan Road. Kucchi | Architectural Value |
| | Yousaf Market | 66/3, | Wada Lane No. 3; | |
| 110. | Unknown | MR-4/ | Adamji Dawood Pota | Architectural Value |
| | | 31. | (Rampart) Road; | |
| | | | , , , , , , , , | |
| 111. | Mansoor Building | MR-4/ | Moosa Lane, Zakariya Lane; | Architectural Value |
| | 8 | 37, | - Larrey Editary & Editey | Themeetain value. |
| 112. | Adam Mosque | MR-5/ | Ali Akbar Street, Zakriya | Architectural Value |
| | 13444 | 56, | Lane; | memeetarar value |
| | | 00, | Barre, | |
| 113. | Unknown | MR-5/ | Thanai Lane; | Architectural Value |
| / | | 80-81, | manui Lane, | menucetarar value |
| 114. | Unknown | MR-6/ | Muhammad Feroz Sheet; | Architectural Value |
| | Cildiowii | 43, | Mulianimad Feroz Sneet, | Architectural value |
| 115. | Unknown | MR-6/ | Markanana d East Charle | A 11 177.7 |
| 110, | Chkhown | 50 E | Muhammad Feroz Street; | Architectural Value |
| 11(| 77.1 | 44, | | |
| 116. | Unknown | MR-6/ | Muhammad Feroz Sheet; | Architectural Value |
| | | 60, | | |
| 117. | Unknown | MR-7/ | Virji Street, Adamji Dawood | Architectural Value |
| | 1 | 3, | Pota (Rampart) Road; | |
| ` | | | • • • | |
| 118. | Unknown | MR-7/ | Weavers Lane, Virji Street; | Architectural Value |
| - | | 11, | | |
| 119. | Unknown | MR-7/ | Weavers Lane, off Adamji | Architectural Value |
| - | | 15, | Dawood Pota (Rampart) | / Inclinectuality / didec |
| | | / | Road; | |
| | | | Modu; | The state of the s |



| 1 | | | | |
|------|---------------------------------|---------------------|--|---------------------|
| /20. | Taswar Manzil | MR-7/ | Muhammad Feroz Street; | Architectural Value |
| 121. | Unknown | 27, MR-7/ | Suleman Lane; | Architectural Value |
| 122. | Unknown | 46, MR-7/ | Weavers Lane; | Architectural Value |
| Í23. | Unknown | 49, MR-7/ 58, | Weavers Lane, Adamji Dawood Pota (Rampart) Road; | Architectural Value |
| 124. | Unknown | MR-7/ 64, 65, | Adamji Dawood Pota (Rampart) Road, Ram Bharti Road; | Architectural Value |
| 125. | Sir Abdullah Haroon Building | MR-1/ 156, | Shahrah-e-Altaf Husain (Napier Road), Kucchi Wada Lane. 1, Karachi | Architectural Value |
| 126. | Alvi Chambers | MR-1/ 162, 163, | Shahrah-e-Altaf Husain (Napier Road), Karachi | Architectural Value |
| 127. | Abdul Hakim Building | MR-2/ 25, | Abdul Majeed Sindhi Road, Marriott Road, Chagla Street, Karachi | Architectural Value |
| 128. | Haji Muhammad Din Building | MR-2/ 24, | Abdul Majeed Sindhi Road, Marriott Road, Karachi | Architectural Value |
| 129. | Khaliq-Un-Nisa Building | MR-2/ 7, | Marriott Road, Fakhr Matri (Newnham) Road, Karachi | Architectural Value |
| 130. | Zeeshan Mill Building | MR-4/ 67, | Qazi Suleman Lane, Karachi | Architectural Value |
| 131. | Unknown | 1/61 | Daryalal Street, Kucchi Wada No. 3 | Architectural Value |

In accordance with Section 6(2) of the Sindh Cultural Heritage (Preservation) Act, 1994, any objection to the issuance of the notification should be addressed to the Government i.e. Culture, Tourism & Antiquities Department, Government of Sindh, within one month from the date of its publication.

Any intentional act to destroy, alter, deface and imperil the Protected Heritage or to build on or near the sites will be unlawful, and punishable under section 18 of the Sindh Cultural Heritage (Preservation) Act, 1994.

-GHULAM AKBAR LAGHARI-

Secretary to Govt. of Sindh Karachi dated the 14th May, 2018

No.OSD/CHC/MRQ-01-49/2017



A copy is forwarded for information and necessary action to:-




- The Chairman Advisory Committee on Sindh Cultural Heritage. 2.
- The Chairman, Planning & Development Board, Govt. of Sindh.
- The Chairman, Technical Committee on Sindh Cultural Heritage. The Administrative Secretaries (All), Government of Sindh.
- The Senior Member, Board of Revenue, Government of Sindh, with request not to partition 5. above heritage properties, without prior approval of Advisory Committee.
- The Commissioner, Karachi. 6.
- The Director General, Sindh Building Control Authority. 7.
- The Director General (Antiquities & Archaeology), CT&AD, Government of Sindh.
- The Director (Heritage), CT&AD, Government of Sindh
- 10. All Members of Advisory / Technical Committee on Sindh Cultural Heritage.
- 11. The Administrator (SZ), Evacuee Trust Properties, Karachi.
- 12. The Chief Executive Officer, Cantonment Board, Karachi.
- 13. The Deputy Commissioner-South, Karachi.
- 14. The Superintendent, Sindh Government Printing Press, Government of Sindh, He is requested to supply 50 copies of the Sindh Government Gazette to this department for official
- 15. PS to Minister of Culture, Tourism & Antiquities Department Government of Sindh, Karachi.
- 16. The Owner / Occupant.
- 17. Notification File.

SECTION OFFICER (HERITAGE)

For Secretary to Govt. of Sindh


KARACHI HERITAGE BUILDINGS RE-SURVEY PROJECT




MARKRT QUARTER

CULTURE, TOURISM AND ANTIQUITIES DEPARTMET GOVERNMENT OF SINDH


01-SULTAN MANSION-MR4



02-FEROZ CHAMBERS-MR1




03-AMJAD BUILDING-MR1



04-HAJI DAWOOD & SONS/UMAIR MANZIL-MR1




05-1/61-MR1



06-ABBAS MANZIL-MR1



07-HYDRI MANZIL-MR1



Abdul Fatah

17-1- 2018

NAME OF INVESTIGATOR:

13.

14.


DATE

heritage due to its social and architectural value.


08-RAHIM MANZIL-MR1



09-1/66/1-MR1




10-SALEEM PARACHA BUILDING-MR1



11-1/74-MR1

| | | 1. IDENTIFICATIO | ON: | | |
|-----|--|------------------------------------|-------------|----------------------|----------------------------|
| | | Site Name: | | 1/74 | |
| | | Other Names: | : | | |
| | | 2. LOCATION: | | | |
| | | Address: | | Kucchi Wada Lane | No.3 |
| | | Survey No. | | Plot No. 1/74 | Sheet No. |
| | | Coordinates | | N-24°51.236 | E-67°00.246 |
| | | District/City/ 1 | Town/ Villa | age: Market Quarte | r's |
| | THE WALL WHITE AND A STREET | 3. OWNERSHIP: | | Private √ | Government |
| | | Name of Owne | er (s) | PRIVATE | |
| | | Khalid | | | |
| 4. | OCCUPANCY: | Complete Commer | | | |
| 5. | REASONS FOR PROTECTION: | Architectural Intere | est: Balcor | | |
| 6. | MEASUREMENT: | Height- 60' | | Length- | Width- 30' |
| 7. | CONSTRUCTION MATERIAL: | Stone Masonry, Cha | | | T |
| 8 | STATUS / PRESENT CONDITION | | ole √ | Good Condition | Needs repair |
| 9. | I DEDENIACI. | | | | |
| 10. | THEREAT(S): LOCATION MAP: | Addition & Alteration PHOTOGRAPHS: | on on top | | |
| | | | on on top | | |
| | LOCATION MAP: | PHOTOGRAPHS: | | ns to be in stable c | ondition. |
| 10. | Location Map | PHOTOGRAPHS: Partially Maintain | ned, seem | | ondition. ed as protected |
| 10. | LOCATION MAP: Location Map COMMENTS: | Partially Maintain The building of | ned, seem | | ed as protected |
| 10. | LOCATION MAP: Location Map COMMENTS: | Partially Maintain The building of | ned, seem | to be declar | ed as protected |


12-JAFRI MANZIL-MR1



13-HAJI IFTIKHAR UDIN BUILDING-MR1

| | | 1. | IDENTIFICATION: | | |
|-----|---|-----|--|-----------------------|---------------------|
| | AND THE RESERVE AND ADDRESS OF THE PARTY OF | | Site Name: | HAJI IFTIKKHAR UD | IN BUILDING |
| | | | | | |
| 7 | | | Other Names: | Muhammad Abdul | lah manzil |
| | | 2. | LOCATION: | | |
| | | | Address: | Kuchhi Wada Lane | no.3, Jodia Bazar |
| | | | Survey No. | Plot No. 1/78 | Sheet No. |
| | A TO | | Coordinates | N-24°51.298 | E-67°00.228 |
| | | | District/City/ Town/ Villa | age: Market Quarter | r's |
| | CHRAL Inches Contain | 3. | OWNERSHIP: | Private √ | Government |
| | W MARKET | | Name of Owner (s) | PRIVATE | |
| | Sum / A | | Abdullah Memon | | |
| 4. | | | plete Commercial | | |
| 5. | REASONS FOR PROTECTION: | | hitectural Interest: Bald apet | conies, Festoon, Pii | asters & Decorative |
| 6. | MEASUREMENT: | Hei | • | Widt | -h- |
| 7. | CONSTRUCTION MATERIAL: | | ne Masonry, Charoli | vviat | .11- |
| 8 | STATUS / PRESENT CONDITION | | pidated Stable V | Good Condition | Needs repair |
| 9. | THEREAT(S): | | roachment | Cood condition | - recus repair |
| 10. | LOCATION MAP: | | OTOGRAPHS: | | |
| | DARYA LAL STREET DARYA LAL STREET REET | | | G COS | MPAN) |
| 11. | COMMENTS: | Par | tially maintained, seem | ns to be in stable co | ondition. |
| 12. | RECOMMENDATIONS | The | e building deserves | to be declar | ed as protected |
| | | 1 | ritage due to its socia | | • |
| 13. | NAME OF INVESTIGATOR: | Abo | dul Fatah | | |
| | | | | | |

14-FARZANA MANZION-MR1




15-Evacuee Trust Building-MR1

| | | 1. | IDENTIFI | CATION: | | |
|--------------|--|-----|--------------|------------------|-----------------------|------------------------|
| | A | | Site Nam | ne: | Evacuee Trust Buil | ding |
| | | | Other Na | ames: | | |
| | | 2. | LOCATIO | ON: | | |
| | O WON | | Address: | | Kucchi Wada Lane | No.1, Jodia Bazar |
| | | | Survey N | lo. | Plot No. 1/136 | Sheet No. |
| | The second of th | | Coordina | | N-24°51.305 | E-67°00.260 |
| | | | District/ | City/ Town/ Vill | age: Market Quarte | r's |
| | | 3. | OWNERS | SHIP: | Private | Government √ |
| | | | | Owner (s) | | GOVERNMENT |
| | | | | Trust Board | | |
| _ | OCCUPANCY | C | , | Government) | | |
| 4. 5. | OCCUPANCY: REASONS FOR PROTECTION: | | mercial | Interest Arche | os Carnisas Dagarat | ive Parapet, Pilasters |
| Э. | REASONS FOR PROTECTION: | | ediments | interest: Arche | es, cornices, Decorat | live Parapet, Phasters |
| 6. | MEASUREMENT: | _ | ight- 45' | l eng | th- 70' W | idth- 50' |
| 7. | CONSTRUCTION MATERIAL: | _ | ne Masoni | | / 0 | |
| 8 | STATUS / PRESENT CONDITION | _ | apidated | Stable √ | Good Condition | Needs repair |
| 9. | THEREAT(S): | Add | dition & Alt | teration on top | , Encroachment | |
| 10. | LOCATION MAP: | PH | OTOGRAPI | HS: | | |
| | DARYA LAL STREET DARYA LAL STREET REET | | | | | |
| 11. | COMMENTS: | rep | pair. | · | | condition and need |
| 12. | RECOMMENDATIONS | Th | e buildi | ng deserves | to be declar | ed as protected |
| | | he | ritage du | ie to its soci | al and architectu | ıral value. |
| 13. | NAME OF INVESTIGATOR: | | dul Fatah | | | |
| 14. | DATE | 16- | 1- 2018 | | | |


16-ISMAIL ABDUL KARIM BUILDING-MR1

| | | 1. | IDENTIFICATION: | | |
|------------|--|------|----------------------------|---------------------------------------|-----------------|
| | | | Site Name: | ISMAIL ABDUL KAR | IM BUILDING |
| | | | Other Names: | | |
| | | | | | |
| | | 2. | LOCATION: | | |
| | | | Address: | Kacchi Wada Lane | No.3 |
| | | | Survey No. | Plot No. 1/94 | Sheet No. |
| | | | Coordinates | N-24°51.251 | E-67°00.241 |
| | The state of the s | | District/City/ Town/ Vill | age: Market Quarte | r's |
| i | | 3. | OWNERSHIP: | Private √ | Government |
| | DAVY - | | Name of Owner (s) | PRIVATE | |
| | | | Mateen | | |
| 4. | OCCUPANCY: | Com | mercial & Residential | | |
| 5. | REASONS FOR PROTECTION: | Arc | hitectural Interest: Arche | s, Balconies, Festoon | & Cornices |
| 6. | MEASUREMENT: | Hei | ght- 60' Lengt | :h- 50' | Width- 40' |
| 7. | CONSTRUCTION MATERIAL: | Sto | ne Masonry, Charoli | | |
| 8 | STATUS / PRESENT CONDITION | Dila | apidated Stable V | Good Condition | Needs repair |
| 9. | THEREAT(S): | Add | dition & Alteration, Encro | ichment | |
| 10. | LOCATION MAP: | | OTOGRAPHS: | | IS IN A |
| | Location Map | | Sitt | | |
| 11. | Location Map COMMENTS: | See | ems to be in stable cond | Tilking of participants | intained. |
| 11. 12. | | | ems to be in stable cond | lition, partially ma | |
| | COMMENTS: | Th | e building deserves | lition, partially ma to be declare | ed as protected |
| | COMMENTS: | The | | lition, partially ma to be declare | ed as protected |

17-TAHIR BHAI PALACE-MR1



18-JUNEJO MANSION-MR1



19-1/115-MR1

| | | IDENTIFICA | TION: | | |
|-----|--|--------------------------|--------------|-----------------------|-----------------|
| | | Site Name: | | 1/115 | |
| | | | | | |
| | | Other Nam | es: | | |
| | | LOCATION: | | | |
| | | Address: | | Near Allied Bank, K | acchi Wada Lane |
| | | | | No.2, Kucchi Galli | |
| | THE PARTY OF THE P | Survey No. | | Plot No. 1/115 | Sheet No. |
| | | Coordinate | | N-24°51.283 | E-67°00.258 |
| | | | | age: Market Quarter | 1 |
| | | OWNERSHI | | Private V | Government |
| | | Name of Ow Abdul Hame | | PRIVATE | |
| 4. | OCCUPANCY: | nmercial | | | |
| 5. | REASONS FOR PROTECTION: | chitectural Int | erest: Arche | S | |
| 6. | MEASUREMENT: | ight- 40' | Lengt | :h- 35' | Width- 25' |
| 7. | CONSTRUCTION MATERIAL: | ne Masonry, | Charoli | | |
| 8 | STATUS / PRESENT CONDITION | | table v | Good Condition | Needs repair |
| 9. | THEREAT(S): | dition & altera | • | | |
| 10. | LOCATION MAP: | OTOGRAPHS: | | | |
| | Location Map Photo / Montage Indicating Streetscape Setting: | | | | |
| 11. | COMMENTS: | rtially maint | ained, seen | ns to be in stable co | ondition. |
| 12. | RECOMMENDATIONS | _ | | | ed as protected |
| | | _ | to its socia | al and architectu | ral value. |
| 13. | NAME OF INVESTIGATOR: | dul Fatah | | | |
| 14. | DATE | -1- 2018 | | | |

20-SULTAN TRANDING & CO.-MR1

| | | 1 IDENTIFICATIONS |
|-----------|------------------------------|--|
| | | 1. IDENTIFICATION: Site Name: SULTAN TRANDING & CO. |
| | | Site Name. |
| | 2 2 2 2 2 | Other Names: |
| | | 2. LOCATION: |
| | | Address: Opposite Meezan Bank, Kacchi Wada |
| | TO TRANSPORT OF THE PARTY OF | Lane No.2 |
| | | Survey No. Plot No. 1/118 Sheet No. |
| | | Coordinates N-24°51.280 E-67°00.253 |
| | | District/City/ Town/ Village: Market Quarter's |
| | | 3. OWNERSHIP: Private V Government |
| | | Name of Owner (s) PRIVATE Arshad Sultan |
| 4. | OCCUPANCY: | omplete Commercial |
| 5. | REASONS FOR PROTECTION: | Architectural Interest: Roundels, Arches, Cornices, Pilaste |
| | | Decorative Parapet, Arcaded Verandah |
| 6. | MEASUREMENT: | Height- 50' Length- 50' Width- 20' |
| 7. | CONSTRUCTION MATERIAL: | Stone Masonry, Charoli |
| 8 | STATUS / PRESENT CONDITION | Dilapidated Stable V Good Condition Needs repair |
| | | |
| 9. 10. | THEREAT(S): LOCATION MAP: | Addition & Alteration, Encroachment PHOTOGRAPHS: |
| | 1 | PHOTOGRAPHS: Sultan Trading Corporation BROTH BROTHERS REPORTED BROTHERS |
| | LOCATION MAP: | PHOTOGRAPHS: Suitan Trading Corporation BROTE |
| 10. | Location Map | PHOTOGRAPHS: Sultan Trading Corporation SUFFE Partially maintained. |
| 11. | Location Map COMMENTS: | PHOTOGRAPHS: Sultan Trading Corporation BROTH BROTHERS REPORTED BROTHERS |
| 11. | Location Map COMMENTS: | PHOTOGRAPHS: Sultan Trading Corporation Brothers Partially maintained. The building deserves to be declared as protected. |

21-ALLAH WALA BUILDING-MR1

| | | 1 | IDENTIFICATION: | | |
|--------------|--|----------|--|---|---|
| | | 1. | Site Name: | ALLAH WALA BUILD | ING |
| | | | Site Nume. | ALLAH WALA BOILD | |
| | To set the | | Other Names: | | |
| | Land San | 2. | LOCATION: | | |
| | MASTER STATE OF THE STATE OF TH | | Address: | BEHIND Denso Hall, | Marriot Road, |
| | | | | Kucchi Wada Lane N | |
| | | | Survey No. | Plot No. 1/130 | Sheet No. |
| | (net) Ifd (Description) | | Coordinates | N-24°51.234 | E-67°00.300 |
| | ale Print Syndicate (PVL) Lee | | District/City/ Town/ Vil | T | |
| | had and a description of the state of the st | 3. | OWNERSHIP: | Private √ | Government |
| | | | Name of Owner (s) | PRIVATE | |
| | OCCUPANCY. | <u> </u> | MULTIPLE | | |
| 4. 5. | OCCUPANCY: REASONS FOR PROTECTION: | | nplete Commercial chitectural Interest: R | oundals Deserative | Daranet Arches |
| 5. | REASONS FOR PROTECTION: | | conies, cornices & Pilaste | • | Parapet, Arches, |
| 6. | MEASUREMENT: | | • | gth- 60' | Width- 40' |
| 7. | CONSTRUCTION MATERIAL: | | one Masonry, Charoli | 311 00 | Width 40 |
| 8 | STATUS / PRESENT CONDITION | _ | apidated Stable V | Good Condition | Needs repair |
| 9. | THEREAT(S): | | croachment, Two new floo | ors built on top | ' |
| 10. | LOCATION MAP: | | OTOGRAPHS: | • | |
| | | | | | |
| | Location Map | - | | | Paint Syndicate (Pvt.) I |
| 11. | N. January Co. | Paul | rtially renovated & see | | Paint Syndicate (Pvt.) |
| 11. 12. | Location Map | | rtially renovated & see e building deserve | ms to be in stable co | Paint Syndicate (Pvt.) I ondition. |
| | Location Map COMMENTS: | Th | | ms to be in stable costs to be declared | Paint Syndicate (Pvt.) I condition. ed as protected |
| | Location Map COMMENTS: | Th he | e building deserve | ms to be in stable costs to be declared | Paint Syndicate (Pvt.) I condition. ed as protected |

22-1/131-MR1

| | | 1. IDENTIFICATION: | | |
|-----|--|-----------------------------------|------------------------|------------------------|
| | | Site Name: | 1/131 | |
| | | | | |
| | | Other Names: | | |
| | | 2. LOCATION: | | |
| | | Address: | | , Kacchi Wada Lane |
| | | | No.1, Marriot Roa | |
| | | Survey No. | Plot No. 1/131 | Sheet No. |
| | CHOLETO TO | Coordinates | N-24°51.237 | E-67°00.293 |
| | | District/City/ Town/ Village | | |
| | The same of the sa | 3. OWNERSHIP: | Private V | Government |
| | | Name of Owner (s) Kamran & Others | PRIVATE | |
| 4. | OCCUPANCY: | Commercial & Residential | | |
| 5. | REASONS FOR PROTECTION: | Architectural Interest: Arches, | Cornices, Pilasters, I | Decorative Parapet & |
| | | Embossed Stone Masonry | | - Состания с такарот с |
| 6. | MEASUREMENT: | Height- 45 Length- | Wic | lth- 40 |
| 7. | CONSTRUCTION MATERIAL: | Stone Masonry, Charoli | | |
| 8 | STATUS / PRESENT CONDITION | Dilapidated Stable V | Good Condition | Needs repair |
| 9. | THEREAT(S): | Addition & Alteration | | |
| | Location Map | | | |
| 11. | COMMENTS: | Partially renovated, seems t | o be in stable con | dition. |
| 12. | RECOMMENDATIONS | The building deserves | | - |
| | | heritage due to its social | and architectura | al value. |
| 13. | NAME OF INVESTIGATOR: | Abdul Fatah | | |
| 13. | | | | |


23-FAIZ-E-ALVI TRUST BUILDING-1-MR1

| | | 1. IDENTIFICATION: | | G+2 |
|-----------------------|--|--|-----------------------|---------------------|
| | | Site Name: | FAIZ-E-ALVI BUILDII | NG |
| | | 0.1 | | |
| | | Other Names: | | |
| | | 2. LOCATION: | | |
| | | Address: | | No.1, Behind 1/160, |
| | TEN PERSONAL PROPERTY OF THE PERSONAL PROPERTY | | Medica Market | |
| | | Survey No. | Plot No. 1/50 | Sheet No. |
| | | Coordinates | N-24°51.277 | E-67°00.276 |
| | | District/City/ Town/ Vill | | |
| | | 3. OWNERSHIP: | Private | Government V |
| | | Name of Owner (s) | | GOVERNMENT |
| | | Evacuee Trust Board | | |
| 4 | OCCUPANCY: | (Federal Government) Complete Commercial | | |
| 4 . 5 . | REASONS FOR PROTECTION: | Architectural Interest: Arc | chas Carnicas Pila | stors & Dosorativo |
| э. | REASONS FOR PROTECTION. | Parapet | illes, Corrices, Fila | sters & Decorative |
| 6. | MEASUREMENT: | | th- 50' | Width- 40' |
| 7. | CONSTRUCTION MATERIAL: | Stone Masonry, Charoli | <u></u> | Wideli 40 |
| 8 | STATUS / PRESENT CONDITION | Dilapidated Stable V | Good Condition | Needs repair |
| | | z mapradeca canale i | | |
| 9. | THEREAT(S): | Encroachment | | |
| 9. 10. | THEREAT(S): LOCATION MAP: | Encroachment PHOTOGRAPHS: | | |
| | | | | |
| | LOCATION MAP: | PHOTOGRAPHS: Seems to be in stable cond | dition but need rep | air. |
| 10. | LOCATION MAP: | PHOTOGRAPHS: Seems to be in stable cond The building deserves | dition but need rep | air. |
| 11. 12. | Location Map: Location Man COMMENTS: RECOMMENDATIONS | PHOTOGRAPHS: Seems to be in stable cond The building deserves heritage due to its social | dition but need rep | air. |
| 11. | Location Map: Location Man COMMENTS: | PHOTOGRAPHS: Seems to be in stable cond The building deserves | dition but need rep | air. |

24-MOHSIN HABIB BUILDING-MR1

| Site Name: Other Names: 2. LOCATION: Address: Near Denso hall, M.A. Jinnah (Bunddar) Road, Marriot Road Survey No. Plot No. 1/144 Sheet No. Coordinates N-24°51.161 E-67°00.278 District/City/ Town/ Village: Market Quarter's 3. OWNERSHIP: Name of Owner (s) Mehtab Ahmed 4. OCCUPANCY: Commercial 5. REASONS FOR PROTECTION: Architectural Interest: Arches, Cornices & Decorative Parapet Height Length 45' Width 20' 7. CONSTRUCTION MATERIAL: Stone Masonry, Charoli 8. STATUS / PRESENT CONDITION Dilapidated Stable v Good Condition Needs repair 10. LOCATION MAP: PHOTOGRAPHS: PHOTOGRAPHS: 11. COMMENTS: Partially maintained, seems to be in stable condition. The building deserves to be declared as protected heritage due to its social and architectural value. Abdul Fatah 14. DATE Other Names: Near Denso hall, M.A. Jinnah (Bunddar) Road, Marriot Road (Bunddar) Road, Marriot Road (Bunddar) Road, Marriot Road (Bunddar) Show. Jinnah (Bunddar) Road, Marriot Road (Bunddar) Show. Jinnah (Bunddar) Road, Marriot Road (Bunddar) Show. Jinnah (Bundar) Show. Jinnah (Bunddar) Show. Jinnah (Bundar) Show. Jinnah (Bunddar) Show. Jinnah (Bundar) Show. Jinn | | | 1. | IDENTIFICATION: | | |
|--|-----|--|-----|---------------------------------------|--------------------|-----------------|
| 2. LOCATION: Address: Near Denso hall, M.A. Jinnah (Bunddar) Road, Marriot Road Survey No. Plot No. 1/144 Sheet No. Coordinates N-24°S1.161 E-67°00.278 District/City/Town/ Village: Market Quarter's 3. OWNERSHIP: Name of Owner (s) Mehtab Ahmed PRIVATE Mehtab Ahmed 4. OCCUPANCY: Commercial REASONS FOR PROTECTION: MEASUREMENT: Height- Length- 45' Width- 20' CONSTRUCTION MATERIAL: Stone Masonry, Charoli THEREAT(S): Encroachment, Addition & Alteration PHOTOGRAPHS: PHOTOGRAPHS: PHOTOGRAPHS: 11. COMMENTS: Partially maintained, seems to be in stable condition. PARTIALLY MARKED AND AND AND AND AND AND AND AND AND AN | - | | | | MOHSIN HABIB BI | JILDING |
| 2. LOCATION: Address: Near Denso hall, M.A. Jinnah (Bunddar) Road, Marriot Road Survey No. Plot No. 1/144 Sheet No. Coordinates N-24°S1.161 E-67°00.278 District/City/Town/ Village: Market Quarter's 3. OWNERSHIP: Name of Owner (s) Mehtab Ahmed PRIVATE Mehtab Ahmed 4. OCCUPANCY: Commercial REASONS FOR PROTECTION: MEASUREMENT: Height- Length- 45' Width- 20' CONSTRUCTION MATERIAL: Stone Masonry, Charoli THEREAT(S): Encroachment, Addition & Alteration PHOTOGRAPHS: PHOTOGRAPHS: PHOTOGRAPHS: 11. COMMENTS: Partially maintained, seems to be in stable condition. PARTIALLY MARKED AND AND AND AND AND AND AND AND AND AN | | SHARING MANAGEMENT | | | | |
| Address: Near Denso hall, M.A. Jinnah (Bunddar) Road, Marriot Road Survey No. Plot No. 1/144 Sheet No. Coordinates N-24°51.161 E-67°00.278 District/City/ Town/ Village: Market Quarter's Name of Owner (s) Nehtab Ahmed OCCUPANCY: Commercial REASONS FOR PROTECTION: REASONS FOR PROTECTION: Stone Masonry, Charoli STATUS / PRESENT CONDITION HEREAT(S): HEREAT(S): COATION MAP: PHOTOGRAPHS: PHOTOGRAPHS: 10. LOCATION MAP: PHOTOGRAPHS: PHOTOGRAPHS: Partially maintained, seems to be in stable condition. The building deserves to be declared as protected heritage due to its social and architectural value. | | | | Other Names: | | |
| Survey No. Piot No. 1/144 Sheet No. | | | 2. | LOCATION: | | |
| Survey No. Plot No. 1/144 Sheet No. Coordinates N-24°51.161 E-67°00.278 District/City/Town/Village: Market Quarter's 3. OWNERSHIP: Private \(\) Government Name of Owner (s) Mehtab Ahmed 4. OCCUPANCY: Commercial 5. REASONS FOR PROTECTION: Architectural interest: Arches, Cornices & Decorative Parapet 6. MEASUREMENT: Height- Length- 45' Width-20' 7. CONSTRUCTION MATERIAL: Stone Masonry, Charoli 8. STATUS / PRESENT CONDITION Dilapidated Stable \(\) Good Condition Needs repair 10. LOCATION MAP: PHOTOGRAPHS: PHOTOGRAPHS: PHOTOGRAPHS: 11. COMMENTS: Partially maintained, seems to be in stable condition. The building deserves to be declared as protected heritage due to its social and architectural value. Abdul Fatah | | | | Address: | Near Denso hall, N | Л.A. Jinnah |
| Coordinates N-24°51.161 E-67°00.278 District/City/ Town/ Village: Market Quarter's 3. OWNERSHIP: Private V Government Name of Owner (s) Mehtab Ahmed 4. OCCUPANCY: Commercial 5. REASONS FOR PROTECTION: Architectural Interest: Arches, Cornices & Decorative Parapet 6. MEASUREMENT: Height- Length- 45' Width-20' 7. CONSTRUCTION MATERIAL: Stone Masonry, Charoli 8 STATUS / PRESENT CONDITION Dilapidated Stable V Good Condition Needs repair 9. THEREAT(S): Encroachment, Addition & Alteration PHOTOGRAPHS: PHOTOGRAPHS: 11. COMMENTS: Partially maintained, seems to be in stable condition. The building deserves to be declared as protected heritage due to its social and architectural value. 13. NAME OF INVESTIGATOR: Abdul Fatah | | | | | (Bunddar) Road, N | Marriot Road |
| District/City/Town/Village: Market Quarter's 3. OWNERSHIP: Private v Government Name of Owner (s) PRIVATE Name of Owner (s) PRIVATE PRIVATE 4. OCCUPANCY: Commercial 5. REASONS FOR PROTECTION: Architectural Interest: Arches, Cornices & Decorative Parapet 6. MEASUREMENT: Height- Length- 45' Width- 20' 7. CONSTRUCTION MATERIAL: Stone Masonry, Charoli 8 STATUS / PRESENT CONDITION Dilapidated Stable v Good Condition Needs repair 9. THEREAT(S): Encroachment, Addition & Alteration PHOTOGRAPHS: PHOTOGRAPHS: 10. COMMENTS: Partially maintained, seems to be in stable condition. 11. COMMENTS: Partially maintained, seems to be declared as protected heritage due to its social and architectural value. 13. NAME OF INVESTIGATOR: Abdul Fatah | | | | • | · | |
| 3. OWNERSHIP: Private v Government Name of Owner (s) Mehtab Ahmed 4. OCCUPANCY: Commercial 5. REASONS FOR PROTECTION: Architectural Interest: Arches, Cornices & Decorative Parapet 6. MEASUREMENT: Height Length 45' Width 20' 7. CONSTRUCTION MATERIAL: Stone Masonry, Charoli 8 STATUS / PRESENT CONDITION Dilapidated Stable v Good Condition Needs repair 10. LOCATION MAP: PHOTOGRAPHS: PHOTOGRAPHS: PHOTOGRAPHS: 11. COMMENTS: Partially maintained, seems to be in stable condition. 12. RECOMMENDATIONS The building deserves to be declared as protected heritage due to its social and architectural value. Abdul Fatah | | | | | | |
| Name of Owner (s) Mehtab Ahmed 4. OCCUPANCY: Commercial 5. REASONS FOR PROTECTION: Architectural Interest: Arches, Cornices & Decorative Parapet 6. MEASUREMENT: Height Length 45' Width 20' 7. CONSTRUCTION MATERIAL: Stone Masonry, Charoli 8 STATUS / PRESENT CONDITION Dilapidated Stable V Good Condition Needs repair 9. THEREAT(S): Encroachment, Addition & Alteration PHOTOGRAPHS: 10. COMMENTS: PHOTOGRAPHS: 11. COMMENTS: Partially maintained, seems to be in stable condition. The building deserves to be declared as protected heritage due to its social and architectural value. 13. NAME OF INVESTIGATOR: Abdul Fatah | | | | District/City/ Town/ Vill | age: Market Quarte | er's |
| Mehtab Ahmed 4. OCCUPANCY: Commercial 5. REASONS FOR PROTECTION: Architectural Interest: Arches, Cornices & Decorative Parapet 6. MEASUREMENT: Height Length 45' Width 20' 7. CONSTRUCTION MATERIAL: Stone Masonry, Charoli 8 STATUS / PRESENT CONDITION Dilapidated Stable v Good Condition Needs repair 9. THEREAT(S): Encroachment, Addition & Alteration PHOTOGRAPHS: PHOTOGRAPHS: 11. COMMENTS: Partially maintained, seems to be in stable condition. 12. RECOMMENDATIONS The building deserves to be declared as protected heritage due to its social and architectural value. 13. NAME OF INVESTIGATOR: Abdul Fatah | | | 3. | | Private √ | Government |
| 4. OCCUPANCY: Commercial 5. REASONS FOR PROTECTION: Architectural Interest: Arches, Cornices & Decorative Parapet 6. MEASUREMENT: Height Length 45' Width-20' 7. CONSTRUCTION MATERIAL: Stone Masonry, Charlos Status / PRESENT CONDITION 9. THEREAT(S): Encroachment, Addition & Alteration 10. LOCATION MAP: PHOTOGRAPHS: PHOTOGRAPHS: 11. COMMENTS: Partially maintained, seems to be in stable condition. 12. RECOMMENDATIONS The building deserves to be declared as protected heritage due to its social and architectural value. Abdul Fatah | | | | | PRIVATE | |
| 5. REASONS FOR PROTECTION: Architectural Interest: Arches, Cornices & Decorative Parapet 6. MEASUREMENT: CONSTRUCTION MATERIAL: STATUS / PRESENT CONDITION 10. LOCATION MAP: PHOTOGRAPHS: 11. COMMENTS: Partially maintained, seems to be in stable condition. 12. RECOMMENDATIONS PHOTOGRAPHS: Partially maintained, seems to be declared as protected heritage due to its social and architectural value. Abdul Fatah | | | | | | |
| 6. MEASUREMENT: Height- Length- 45' Width-20' 7. CONSTRUCTION MATERIAL: Stone Masonry, Charoli 8 STATUS / PRESENT CONDITION Dilapidated Stable V Good Condition Needs repair 9. THEREAT(S): Encroachment, Addition & Alteration PHOTOGRAPHS: PHOTOGRAPHS: 11. COMMENTS: Partially maintained, seems to be in stable condition. 12. RECOMMENDATIONS The building deserves to be declared as protected heritage due to its social and architectural value. Abdul Fatah | | | | | | |
| 7. CONSTRUCTION MATERIAL: 8 STATUS / PRESENT CONDITION 9. THEREAT(S): LOCATION MAP: PHOTOGRAPHS: 11. COMMENTS: Partially maintained, seems to be in stable condition. Partiage due to its social and architectural value. 13. NAME OF INVESTIGATOR: Dilapidated Stable v Good Condition Needs repair Fencroachment, Addition & Alteration PHOTOGRAPHS: Partially maintained, seems to be in stable condition. The building deserves to be declared as protected heritage due to its social and architectural value. | | | | | | |
| STATUS / PRESENT CONDITION Dilapidated Stable V Good Condition Needs repair Encroachment, Addition & Alteration PHOTOGRAPHS: PHOTOGRAPHS: Location Map The Comments: Partially maintained, seems to be in stable condition. The building deserves to be declared as protected heritage due to its social and architectural value. Abdul Fatah | | | | <u> </u> | 45' | Width- 20' |
| 9. THEREAT(S): LOCATION MAP: PHOTOGRAPHS: PHOTOGRAPHS: 11. COMMENTS: RECOMMENDATIONS Partially maintained, seems to be in stable condition. The building deserves to be declared as protected heritage due to its social and architectural value. Abdul Fatah | | | | • | T | T |
| 11. COMMENTS: Partially maintained, seems to be in stable condition. The building deserves to be declared as protected heritage due to its social and architectural value. Abdul Fatah | | - | | • | | Needs repair |
| 11. COMMENTS: Partially maintained, seems to be in stable condition. 12. RECOMMENDATIONS The building deserves to be declared as protected heritage due to its social and architectural value. Abdul Fatah | | | _ | · · · · · · · · · · · · · · · · · · · | literation | |
| 12. RECOMMENDATIONS The building deserves to be declared as protected heritage due to its social and architectural value. 13. NAME OF INVESTIGATOR: Abdul Fatah | | T ROAD RY TY ON A JANUAR (BUNDER) ROAD | | | | |
| heritage due to its social and architectural value. 13. NAME OF INVESTIGATOR: Abdul Fatah | 11. | COMMENTS: | Pa | rtially maintained, seer | ns to be in stable | condition. |
| 13. NAME OF INVESTIGATOR: Abdul Fatah | 12. | RECOMMENDATIONS | Th | e building deserves | s to be declar | ed as protected |
| 7.00011.0011 | | | he | ritage due to its soci | al and architect | ural value. |
| 14. DATE 2-1- 2018 | 13. | NAME OF INVESTIGATOR: | Ab | dul Fatah | | |
| | 14. | DATE | 2-1 | - 2018 | | |


25-FIDA HUSSAIN QADIR BHAI BUILDING-MR1



26-SETH BHAI BUILDING-MR1

| | | 1. | IDENTIFICATION: | | | | |
|------------|--|--------------|------------------------------------|--|---------------------|--|--|
| | | | Site Name: | SETH BHAI BUILIDN | G | | |
| | 1225 IN | | | | | | |
| | | Other Names: | | SAEDEE BHAI | | | |
| | PARTITION OF THE PARTIT | 2. LOCATION: | | | | | |
| | | | | Beside 1/158,60 No | - | | |
| | | | | Daryalal Street, Dar Market | ndiya Bazar, Chawal | | |
| | | | Survey No. | Plot No. 1/154 | Sheet No. | | |
| | | | Coordinates | N-24°51.392 | E-67°00.275 | | |
| | "Maronal Strongar Costs | | District/City/ Town/ Vill | age: Market Quarter | 's | | |
| | | 3. | OWNERSHIP: | Private √ | Government | | |
| | | | Name of Owner (s) | PRIVATE | | | |
| | | | Ahmed Dehli Wala | | | | |
| 4. | OCCUPANCY: | | mplete Commercial | | | | |
| 5. | REASONS FOR PROTECTION: | | chitectural Interest: Rou | undels, Arches, Ped | iments, Cornices & | | |
| 6. | MEASUREMENT: | | corative Parapet ight- 50' Leng | th- 30' | Width- 20' | | |
| 7. | CONSTRUCTION MATERIAL: | - | one Masonry, Charoli | uii- 30 | Width- 20 | | |
| 8 | STATUS / PRESENT CONDITION | | apidated Stable V | Good Condition | Needs repair | | |
| 9. | THEREAT(S): | | croachment | dood condition | Neeus repair | | |
| 10. | LOCATION MAP: | - | OTOGRAPHS: | | | | |
| | | | | | | | |
| | DARYA LAL STREET OR AND THE STR | | | ACC COMPANY OF THE PARTY OF THE | | | |
| 11. | Sente Man | See | ems to be partially crac | ked but in stable co | endition. | | |
| 11. 12. | Location Map | See | | | | | |
| | Location Map | Th | | s to be declare | ed as protected | | |
| | Location Map | Th he | e building deserves | s to be declare | ed as protected | | |

27-RAZAQUE CHAMBER-MR1




28-S.NAWAB BROTHERES-MR1



| 1. | IDENTIFICATION: | | |
|----|----------------------------|---------------------------------------|-------------|
| | Site Name: | S.NAWAB BROTHERS | |
| | Other Names: | | |
| 2. | LOCATION: | | |
| | Address: | Sharah-e-Altaf Hussain(Napier Road), | |
| | | Kacchi Wada Lane N | No.1 |
| | Survey No. | Plot No. 1/160 | Sheet No. |
| | Coordinates | N-24°51.273 | E-67°00.299 |
| | District/City/ Town/ Villa | age: Market Quarter | 's |
| 3. | OWNERSHIP: | Private √ | Government |
| | Name of Owner (s) | PRIVATE | |
| | S.NAWAB | | |

| 4. | OCCUPANCY: Commercial | | | | |
|----|----------------------------|---|------------------------|----------------|--------------|
| 5. | REASONS FOR PROTECTION: | Architectural Interest: Arches, Cornices & Decorative Parapet | | | |
| 6. | MEASUREMENT: | Height- 30' | Leng | th- 60' | Width- 23' |
| 7. | CONSTRUCTION MATERIAL: | Stone Mason | Stone Masonry, Charoli | | |
| 8 | STATUS / PRESENT CONDITION | Dilapidated | Stable √ | Good Condition | Needs repair |
| 9. | THEREAT(S): | | | | |


LOCATION MAP: 10.





| 1 | | | | |
|-----|-----------------------|---|--|--|
| 11. | COMMENTS: | Partially maintained but seems to be in stable condition. | | |
| 12. | RECOMMENDATIONS | The building deserves to be declared as protected heritage due to its social and architectural value. | | |
| | | Theritage due to its social and architectural value. | | |
| 13. | NAME OF INVESTIGATOR: | Abdul Fatah | | |
| 14. | DATE | 16-1- 2018 | | |


29-MADINA CENTER-MR1



| 1. | IDENTIFICATION: | | |
|----|----------------------------|----------------------|-----------------|
| | Site Name: | 1/167 | |
| | Other Names: | Madina Centre | |
| 2. | LOCATION: | | |
| | Address: | Beside Denso hall, S | harah-e-Altaf |
| | | Hussain (Napier Roa | d), Kucchi Wada |
| | | Lane No.1 | |
| | Survey No. | Plot No. 1/167 | Sheet No. |
| | Coordinates | N-24°51.219 | E-67°00.298 |
| | District/City/ Town/ Villa | age: Market Quarter' | S |
| 3. | OWNERSHIP: | Private √ | Government |
| | Name of Owner (s) | PRIVATE | |
| | N.P Trust | | |

| 4. | OCCUPANCY: | Complete Com | mercial | | | |
|----|----------------------------|---------------|---------------|-------------------|----------------|----------|
| 5. | REASONS FOR PROTECTION: | Architectural | Interest: Arc | hes, Roundals, Co | rnices, Emboss | ed stone |
| | | masonry & Pil | asters | | | |
| 6. | MEASUREMENT: | Height- | Length- | · W | idth- | |
| 7. | CONSTRUCTION MATERIAL: | Stone Masoni | y, Charoli | | | |
| 8 | STATUS / PRESENT CONDITION | Dilapidated | Stable √ | Good Condition | Needs r | epair |
| 9. | THEREAT(S): | Encroachmen | t | | | |

10. LOCATION MAP:



PHOTOGRAPHS:





| 11. | COMMENTS: | Partially maintained and seems to be in stable condition. Most part of this building has been renovated. |
|-----|-----------------------|--|
| 12. | RECOMMENDATIONS | The building deserves to be declared as protected heritage due to its social and architectural value. |
| 13. | NAME OF INVESTIGATOR: | Abdul Fatah |
| 14. | DATE | 16-1- 2018 |


30-FAIZAN-E-HUSSAIN BUILDING NO.5-MR2



| 1. | IDENTIFICATION: | | | |
|----|----------------------------|-------------------------------------|-------------|--|
| | Site Name: | FAIZAN-E-HUSSAIN BUILDING NO.5 | | |
| | Other Names: | M.S & Company | | |
| 2. | LOCATION: | | | |
| | Address: | Marriot Road, Fakhr Matri (Newnham) | | |
| | | Road | | |
| | Survey No. | Plot No. 2/12 | Sheet No. | |
| | Coordinates | N-24°51.173 | E-67°00.168 | |
| | District/City/ Town/ Villa | age: Market Quarte | r's | |
| 3. | OWNERSHIP: | Private √ | Government | |
| | Name of Owner (s) | PRIVATE | | |
| | M.S & Others | | | |

| 4. | OCCUPANCY: | Complete Commercial | | | |
|----|----------------------------|---|---|----------------|--------------|
| 5. | REASONS FOR PROTECTION: | Architectural Interest: Balconies, Geometrical design parapet | | | |
| 6. | MEASUREMENT: | Height- 60' Length- 70' Width- 30' | | Width- 30' | |
| 7. | CONSTRUCTION MATERIAL: | Stone Masonry, Charoli | | | |
| 8 | STATUS / PRESENT CONDITION | Dilapidated | Stable v | Good Condition | Needs repair |
| 9. | THEREAT(S): | Encroachmen | Encroachment, One floor Addition & Alteration | | |
| | | | | | |

LOCATION MAP: 10.



PHOTOGRAPHS:



| 11. | COMMENTS: | Seems to be in good condition. | | |
|-----|-----------------------|---|--|--|
| 12. | RECOMMENDATIONS | The building deserves to be declared as protected heritage due to its social and architectural value. | | |
| 13. | NAME OF INVESTIGATOR: | Abdul Fatah | | |
| 14. | DATE | 26-1- 2018 | | |

31-BHAI JAN BUILDING-MR2

| | | 1. | IDENTIFICATION: | | |
|------------|--|---|--|------------------------|---|
| | | | Site Name: | BHAI JAN BUILDING | i |
| | | | Other Names: | Bhai Jan Market | |
| | | 2. | LOCATION: | | |
| | | | Address: | Abdul Majid Sindhi | Road, Marriot Road |
| | | | Survey No. | Plot No. 2/23 | Sheet No. |
| | | | Coordinates | N-24°51.166 | E-67°00.146 |
| | | | District/City/ Town/ Vil | age: Market Quarter | 's |
| | THE STATE OF THE S | 3. | OWNERSHIP: | Private √ | Government |
| | MARIA CONTRACTOR OF THE PARTY O | | Name of Owner (s) | PRIVATE | 1 |
| | | | Yousaf & other | | |
| 4. | OCCUPANCY: | Co | mplete Commercial | | |
| 5. | REASONS FOR PROTECTION: | Architectural Interest: Roundels, Rectangle | | | |
| 6. | MEASUREMENT: | Height- 60' Length- 70' Width- 20' | | Width- 20' | |
| 7. | CONSTRUCTION MATERIAL: | Sto | ne Masonry, Charoli | | |
| 8 | STATUS / PRESENT CONDITION | Dila | apidated Stable √ | Good Condition | Needs repair |
| 9. | THEREAT(S): | Enc | croachment, one floor Add | dition & alteration on | top |
| | 80 - 2 - 20-22 - 22 - 22 - 22 - 24 - 24 - | | | | |
| | Location Map | | | | الله الله الله الله الله الله الله الله |
| 11. | RANN BERN COLD NAME OF THE PROPERTY OF THE PRO | See | ems to be in stable con- | dition. | 1000 B |
| 11. 12. | Location Map | | ems to be in stable concept building deserve | | ed as protected |
| | Location Map COMMENTS: | Th | | s to be declare | |
| | Location Map COMMENTS: | Th he | e building deserve | s to be declare | |

32-KARACHI MUSLIM RESTURANT-MR2



33-LAKSHIMI BUILDING-MR2

| | | 1. IDENTIFICATION: | | |
|-----|--|---|--|--|
| - | | Site Name: LAKSHIMI BUILDING | | |
| | | | | |
| | THE STATE OF THE S | Other Names: | | |
| | | 2. LOCATION: | | |
| | | Address: M.A. Jinnah (Bunder) Road, Chagla Road | | |
| | | , Bolton Market | | |
| | | Survey No. Plot No. 2/32 Sheet No. | | |
| | | Coordinates N-24°51.140 E-67°00.146 | | |
| | The same of the | District/City/ Town/ Village: Market Quarter's | | |
| | | 3. OWNERSHIP: Private √ Government | | |
| | SLINSTAR | Name of Owner (s) PRIVATE | | |
| | THE COURSE | Ahmed Tarique | | |
| 4. | OCCUPANCY: | Complete Commercial | | |
| 5. | REASONS FOR PROTECTION: | Architectural Interest: Decorative Parapet, Louvers & Clock Tower | | |
| 6. | MEASUREMENT: | Height- Length- Width- | | |
| 7. | CONSTRUCTION MATERIAL: | Stone Masonry, Charoli | | |
| 8 | STATUS / PRESENT CONDITION | Dilapidated Stable √ Good Condition Needs repair | | |
| 9. | THEREAT(S): | Addition & Alteration, Encroachment | | |
| 10. | LOCATION MAP: | PHOTOGRAPHS: | | |
| | To the second of | | | |
| 11. | COMMENTS: | Well maintained. | | |
| 12. | RECOMMENDATIONS | The building deserves to be declared as protected | | |
| | | heritage due to its social and architectural value. | | |
| 13. | NAME OF INVESTIGATOR: | Abdul Fatah | | |
| 13. | | 11-1- 2018 | | |


34-ZAMINDAR MARKET- MR2



| 1. | IDENTIFICATION: | | | | |
|----|----------------------------|---------------------------------------|-------------|--|--|
| | Site Name: | ZAMINDAR MARKET | | | |
| | Other Names: | | | | |
| 2. | LOCATION: | | | | |
| | Address: | M.A. Jinnah (Bunder) Road, Ram Bharti | | | |
| | | Street | | | |
| | Survey No. | Plot No. 2/35 | Sheet No. | | |
| | Coordinates | N-24°51.145 | E-67°00.206 | | |
| | District/City/ Town/ Villa | age: Market Quarter' | S | | |
| 3. | OWNERSHIP: | Private √ | Government | | |
| | Name of Owner (s) | PRIVATE | | | |
| | Shakela Ahmed Tanoli | | | | |

| 4. | OCCUPANCY: | Commercial | | | |
|----|----------------------------|----------------|------------------|--------------------------|--------------|
| 5. | REASONS FOR PROTECTION: | Architectural | Interest: Balcoi | nies, Pilasters & Decora | tive parapet |
| 6. | MEASUREMENT: | Height- | Length- | Width- | • |
| 7. | CONSTRUCTION MATERIAL: | Stone Masonr | y, Charoli | | |
| 8 | STATUS / PRESENT CONDITION | Dilapidated | Stable √ | Good Condition | Needs repair |
| 9. | THEREAT(S): | Addition & Alt | eration | | |

10. LOCATION MAP:




PHOTOGRAPHS:






| 11. | COMMENTS: | Partially maintained. | | | | |
|-----|-----------------------|---|--|--|--|--|
| 12. | RECOMMENDATIONS | The building deserves to be declared as protected | | | | |
| | | heritage due to its social and architectural value. | | | | |
| 13. | NAME OF INVESTIGATOR: | Abdul Fatah | | | | |
| 14. | DATE | 11-1- 2018 | | | | |


35-2/47-MR2




36-LOTIA BUILDING- MR2



37-3/3- MR3



38-3/4- MR3



39-HALANA MANSION-MR4

| | STATE AND STATE OF THE STATE OF | 1. | IDENTIFIC | ATION: | | G+2+1 |
|-----|--|-----|--------------|----------------|-----------------------|---------------------------------------|
| | | | Site Nam | e: | HALANA MANSIO | N |
| | | | Other Na | mes: | | |
| | | 2. | LOCATIO | N: | | |
| | | | Address: | | Near Achi Qabar, | Ali Akber Street, Jodia |
| | | | | | Bazar | · |
| | WIT SHOT SHOW IN SHOW | | Survey No | o. | Plot No. 4/10 | Sheet No. |
| | | | Coordina | | N-24°51.339 | E-67°00.062 |
| | | | District/C | ity/ Town/ Vil | lage: Market Quarte | er's |
| | | 3. | OWNERSI | HIP: | Private √ | Government |
| | | | Name of 0 | Owner (s) | PRIVATE | |
| | | | Dewan Ch | | | |
| | | | Mansoor | & others | | |
| 4. | OCCUPANCY: | _ | mercial & F | | | |
| 5. | REASONS FOR PROTECTION: | _ | | | es, Balconies & Corni | |
| 6. | MEASUREMENT: | _ | ght- 60' | Leng | th- | Width- |
| 7. | CONSTRUCTION MATERIAL: | | ne Masonry | | T | |
| 8 | STATUS / PRESENT CONDITION | | apidated | Stable V | Good Condition | Needs repair |
| 9. | THEREAT(S): | | | | Iteration on top | |
| 10. | LOCATION MAP: | PH | OTOGRAPH | S : | | |
| | THE E | | | | | 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 |
| | Location Map | | | | | |
| 11. | COMMENTS: | Pai | rtially main | ntained and | facade seems to be | e in good condition. |
| 12. | RECOMMENDATIONS | Th | e buildin | g deserve | s to be declar | ed as protected |
| | | | | • | al and architect | • |
| 13. | NAME OF INVESTIGATOR: | | dul Fatah | | | |
| 14. | | 26- | | | | |

40-NOOR BHAI HOUSE-MR4

| | | 1. | IDENTIFIC | CATION: | | |
|-----|--|------|-------------|------------------|------------------------------------|-----------------------------|
| | | | Site Nam | e: | NOOR BHAI HOUS | SE |
| | | | Other Na | imes: | | |
| | | 2. | LOCATIO | N: | | |
| | | | Address: | | Adamjee Dawood | Pota (Rampart) Road |
| | | | Survey N | 0. | Plot No. 4/28 | Sheet No. |
| | | | HOUSE | | N-24°51.226 | E-67°00.081 |
| | | | District/0 | City/ Town/ Vill | age: Market Quarto | er's |
| | | 3. | OWNERS | HIP: | Private √ | Government |
| | HRI MADULINE MONTH POR | | Name of | Owner (s) | PRIVATE | |
| | TIPLE STATE OF THE | | | nk & Others | | |
| 4. | OCCUPANCY | Comp | lete Comm | nercial | 1 | |
| 5. | REASONS FOR PROTECTION: | Arc | hitectural | Interest: Arche | es & Cornices | |
| 6. | MEASUREMENT: | Hei | ght- 55' | Leng | th- 50' | Width- 15' |
| 7. | CONSTRUCTION MATERIAL: | Sto | ne Masonr | y, Charoli | | |
| 8 | STATUS / PRESENT CONDITION | | apidated | Stable √ | Good Condition | Needs repair |
| 9. | THEREAT(S): | End | roachment | t, Addition & A | lteration | |
| | Location Map | | | | | |
| 11. | COMMENTS: | Coi | mpletely re | novated. | | |
| 12. | RECOMMENDATIONS | | | | s to be declar al and architect | ed as protected ural value. |
| 13. | NAME OF INVESTIGATOR: | _ | dul Fatah | | | · · · · · · |
| 14. | DATE | _ | 1- 2018 | | | |
| | | | - 2010 | | | |


41-MANSOOR BUILDING-MR4

| | | 1. IDENTIFICATION: | | |
|------------|--|---|------------------------|---------------------------------------|
| | | Site Name: | MANSOOR BUILDIN | IGG |
| | | Other Names: | Mandvi Wala Build | ing |
| | 11 6 | 2. LOCATION: | | |
| | | Address: | Moosa Lane, Zakar | ya Lane |
| | A TO THE REAL PROPERTY OF THE PARTY OF THE P | Survey No. | Plot No. 4/38 | Sheet No. |
| | | Coordinates | N-24°51.266 | E-67°00.100 |
| | | District/City/ Town/ V | illage: Market Quarter | 's |
| | | 3. OWNERSHIP: | Private √ | Government |
| | | Name of Owner (s) | | |
| | | Anees Bhai | | |
| 4. | OCCUPANCY: | Commercial | | |
| 5. | REASONS FOR PROTECTION: | Architectural Interest: Balo | onies & Cornices | |
| 6. | MEASUREMENT: | Height -54' Lengt | th- 15' | Width- 10' |
| 7. | CONSTRUCTION MATERIAL: | Stone Masonry, Charoli | | |
| 8 | STATUS / PRESENT CONDITION | Dilapidated Stable √ | Good Condition | Needs repair |
| 9. | THEREAT(S): | Encroachment, Addition & | Alteration | |
| 10. | LOCATION MAP: | PHOTOGRAPHS: | | |
| | | | | |
| | Location Map | | | |
| 11. | 3 NOMIN 98 | Partially maintained. | | |
| 11. 12. | Location Map | Partially maintained. The building deserved | es to be declare | ed as protected |
| | Location Map COMMENTS: | - | | · · · · · · · · · · · · · · · · · · · |
| | Location Map COMMENTS: | The building deserve | | • |

42-HAJI YOUSUF MANZIL- MR4

| 1. IDENTIFICATION: Site Name: HAJI YOUSUF MA | |
|--|-------------------------|
| | ANZIL |
| | |
| Other Names: | |
| 2. LOCATION: | |
| Address: Zakariya Lane, be | eside Mansoor Building, |
| Near Temple | |
| Survey No. Plot No. 4/39 | Sheet No. |
| Coordinates N-24°51.257 | E-67°00.083 |
| District/City/ Town/ Village: Market Quar | ter's |
| 3. OWNERSHIP: Private √ | Government |
| Name of Owner (s) PRIVATE | |
| Haji Yousaf | |
| 4. OCCUPANCY: Commercial & Residential | |
| 5. REASONS FOR PROTECTION: Architectural Interest: Balconies, Pilasters, | Cornices & Decorative |
| Parapet | |
| 6. MEASUREMENT: Height- 55' Length- 50' | Width- 35' |
| 7. CONSTRUCTION MATERIAL: Stone Masonry, Charoli | |
| 8 STATUS / PRESENT CONDITION Dilapidated Stable √ Good Condition | Needs repair |
| 9. THEREAT(S): Encroachment, Addition & Alteration 10. LOCATION MAP: PHOTOGRAPHS: | |
| ABIS BANK Rampart Row B POTA (RAMPART) ROAD Location Map | |
| 11. COMMENTS: Seems to be in stable condition but need re | epair. |
| | ared as protected |
| 12. RECOMMENDATIONS The building deserves to be decl | |
| 12. RECOMMENDATIONS The building deserves to be decliberated by t | tural value. |
| | tural value. |

43-KHORI GARDEN (MUSLAH UDDIN)-MR1



44-HAFIZ MUHAMMAD YOUSAF MARKET-MR1

| | THE MAN STORY A MAN | 1. | IDENTIFICATION: | | |
|--------------|--|--------|--|--------------------|--------------------|
| | | | Site Name: | HAFIZ MUHAMMA | AD YOUSAF MARKET |
| | | | Other Names: | | |
| | | 2. | LOCATION: | | |
| 0 | | | Address: | Opposite Khori gar | rden, Near Alfalah |
| 31 | | | | Bank, Murad Khan | Road, Kachhi Wada |
| 17 | | | | Lane No:3 | |
| m - 1 | | | Survey No. | Plot No. 1/66/3 | Sheet No. |
| | | | Coordinates | N-24°51.252 | E-67°00.216 |
| | | | District/City/ Town/ Villa | _ | |
| | | 3. | OWNERSHIP: | Private V | Government |
| | | | Name of Owner (s) | PRIVATE | |
| | | | Hafiz Muhammad Yousaf | | |
| 1 | OCCUPANCY: Co | mme | rcial & Residential | | |
| 4. 5. | REASONS FOR PROTECTION: | | hitectural Interest: Ba | lconies Arches (| Cornices Roundels |
| J. | REASONS FOR FROTEETION. | 1 | sters, Pediments (Crown o | | |
| 6. | MEASUREMENT: | _ | · · · · · · · · · · · · · · · · · · · | :h- 60' | Width- 40' |
| 7. | CONSTRUCTION MATERIAL: | - | ne Masonry, Charoli | <u> </u> | |
| 8 | STATUS / PRESENT CONDITION | - | apidated Stable V | Good Condition | Needs repair |
| 9. | THEREAT(S): | Enc | roachment | | |
| 10. | LOCATION MAP: | PHO | OTOGRAPHS: | | |
| | LANE ON CATAL ON CATAL | | | | |
| | Location Map | | | | |
| 11. | Location Map COMMENTS: | _ | cade seems to be in stal | | - |
| 11. 12. | Location Map | Th | e building deserves | to be declare | ed as protected |
| 12. | COMMENTS: RECOMMENDATIONS | The | e building deserves ritage due to its socia | to be declare | ed as protected |
| | Location Map COMMENTS: | The he | e building deserves | to be declare | ed as protected |


45-5/110/2-MR5



| 1. | IDENTIFICATION: | | |
|----|----------------------------|--------------------|-------------|
| | Site Name: | 5/110/2 | |
| | | | |
| | Other Names: | | |
| | | | |
| 2. | LOCATION: | | |
| | Address: | Daryalal Street | |
| | Survey No. | Plot No. 5/110/2 | Sheet No. |
| | Coordinates | N-24°51.306 | E-67º00.097 |
| | District/City/ Town/ Villa | age: Market Quarte | r's |
| 3. | OWNERSHIP: | Private √ | Government |
| | Name of Owner (s) | PRIVATE | |
| | Athar & Others | | |

| 4. | OCCUPANCY: | Complete Commercial | | | | | |
|----|----------------------------|---|------------------------|----------------|--------------|--|--|
| 5. | REASONS FOR PROTECTION: | Architectural Interest: Arches, Cornices, Pilasters | | | | | |
| 6. | MEASUREMENT: | Height- 50' | Length | - 45′ | Width- 40' | | |
| 7. | CONSTRUCTION MATERIAL: | Stone Masonry | Stone Masonry, Charoli | | | | |
| 8 | STATUS / PRESENT CONDITION | Dilapidated | Stable √ | Good Condition | Needs repair | | |
| 9. | THEREAT(S): | Addition & alteration, Encroachment | | | | | |

10. LOCATION MAP:











| 11. | COMMENTS: | Partially renovated. | | | | |
|-----|-----------------------|---|--|--|--|--|
| 12. | RECOMMENDATIONS | The building deserves to be declared as protected heritage due to its social and architectural value. | | | | |
| 13. | NAME OF INVESTIGATOR: | Abdul Fatah | | | | |
| 14. | DATE | 19-1- 2018 | | | | |


46-5/110/1-MR5



47-MALIK BHAI BUILIDNG-MR5



48-JHOOLAY LAL TEMPEL-MR5



Abdul Fatah 19-1- 2018

RECOMMENDATIONS

NAME OF INVESTIGATOR:

12.

13.


14.

DATE

The building deserves to be declared as protected

heritage due to its social and architectural value.

49-5/140-MR5



50-SONERI BANK BUILDING-MR5




51-6/14-MR6

| 1 | | 1. | IDENTIFICATION: | 193 | 36 |
|------------|---|------|--|-----------------------|-------------------------|
| | | | Site Name: | 6/14 | |
| | | | | | |
| | | | Other Names: | | |
| | | 2. | LOCATION: | | |
| | | | Address: | Behind Dubai Islan | nic Bank, Virji street, |
| | | | | Khund Street, Jodi | |
| ļ | | | Survey No. | Plot No. 6/14 | Sheet No. |
| | | | Coordinates | N-24°51.282 | E-67°00.097 |
| | Des stars Co. | | District/City/ Town/ Vill | - | r's |
| ļ | | 3. | OWNERSHIP: | Private √ | Government |
| | | | Name of Owner (s) MULTIPLE | PRIVATE | |
| 4. | OCCUPANCY: | Comn | nercial | | |
| 5. | REASONS FOR PROTECTION: | Arc | hitectural Interest: Balcon | nies, Pilasters & Dec | orative Parapet |
| 6. | MEASUREMENT: | Hei | ght-65' Lengt | :h- 40' | Width- 20' |
| 7. | CONSTRUCTION MATERIAL: | Sto | ne Masonry, Charoli | | |
| 8 | STATUS / PRESENT CONDITION | Dila | apidated Stable V | Good Condition | Needs repair |
| 9. | THEREAT(S): | Add | dition & alteration, encro | achment | |
| 10. | LOCATION MAP: | PH | OTOGRAPHS: | | |
| | SRAIS SIREEL & | | | | |
| | Location Map | | | | |
| 11. | AND | Par | rtially maintained and s | eems to be in stab | ole condition. |
| 11. 12. | Location Map | | rtially maintained and see building deserves | | |
| 12. | COMMENTS: RECOMMENDATIONS | The | e building deserves | to be declar | ed as protected |
| | Location Map COMMENTS: | The | e building deserves | to be declar | ed as protected |


52-ARFAT CHAMBER-MR5

| | | 1. | IDENTIFICATION: | | |
|-----------|---|-----|----------------------------|---------------------|-------------------|
| | | | Site Name: | ARFAT CHAMBER | |
| | | | Other Names: | | |
| | | 2. | LOCATION: | | |
| | | | Address: | Behind Sharifi Masj | iid, Zakriya lane |
| İ | d' la | | Survey No. | Plot No. 5/128 | Sheet No. |
| | | | Coordinates | N-24°51.265 | E-67°00.102 |
| | | | District/City/ Town/ Vill | age: Market Quarter | 's |
| | | 3. | OWNERSHIP: | Private √ | Government |
| | | | Name of Owner (s) | PRIVATE | |
| | | | Haji Suleman & Others | | |
| 4. | | | mercial | | |
| 5. | REASONS FOR PROTECTION: | | hitectural Interest: Arche | | • |
| 6. | MEASUREMENT: | | | :h- 20' | Width- 10' |
| 7. | CONSTRUCTION MATERIAL: | | ne Masonry, Charoli | T | |
| 8 | STATUS / PRESENT CONDITION | | apidated Stable √ | Good Condition | Needs repair |
| 9. 10. | THEREAT(S): LOCATION MAP: | _ | croachment OTOGRAPHS: | | |
| | Location Map | | | | |
| 11. | COMMENTS: | Pai | rtially maintained. | | |
| 12. | RECOMMENDATIONS | l | e building deserves | | |
| 13. | NAME OF INVESTIGATOR: | | dul Fatah | ar and architectu | idi fuluci |
| 14. | DATE | | 1- 2018 | | |
| | 1 | | | | |

53-SOPARIWALA BUILDING-MR6



54-6/21-MR6



55-6/20-MR6

| | N. C. | 1. | IDENTIFICATION: | | G+3+1 |
|-----------|----------------------------|-----|---|--------------------------|--------------------------|
| | | | Site Name: | 6/20 | |
| | | | Other Names: | | |
| | | | Other Names. | | |
| | | 2. | LOCATION: | | |
| | | | Address: | Near Sharifi masjid | , Virji street, Abdul |
| | | | | Rehman Street | |
| | | | Survey No. | Plot No. 6/20 | Sheet No. E-67°00.111 |
| | | | Coordinates District/City/ Town/ Vill | N-24 ^o 51.244 | |
| | | _ | | | |
| | | 3. | OWNERSHIP: | Private √ PRIVATE | Government |
| | | | Name of Owner (s) Nasir Khatak | PRIVATE | |
| 4. | OCCUPANCY: | Com | plete Commercial | | |
| 5. | REASONS FOR PROTECTION: | Arc | hitectural Interest: Embo | ssed stone masonry, | Arches |
| 6. | MEASUREMENT: | Hei | ght- 435' Len | gth- 25' | Width- 15' |
| 7. | CONSTRUCTION MATERIAL: | _ | ne Masonry, Charoli | | |
| 8 | STATUS / PRESENT CONDITION | | pidated Stable √ | Good Condition | Needs repair |
| 9. 10. | THEREAT(S): LOCATION MAP: | | lition & alteration on top, DTOGRAPHS: | Encroachment | |
| | Location Map | | | | |
| 11. | COMMENTS: | See | ems to be in stable cond | dition. | |
| 12. | RECOMMENDATIONS | | e building deserves | | ed as protected |
| | | | ritage due to its socia | | • |
| 13. | NAME OF INVESTIGATOR: | | dul Fatah | | |
| 14. | DATE | | 1- 2018 | | |
| | <u> </u> | | | | |

56-ABDUL ALI AZIZ MUHAMMAD-MR6



57-6/1-MR6


| 1. IDENTIFICATION: Site Name: Other Names: 2. LOCATION: Address: Beside MCB bank, Daryalal street, V street Survey No. Plot No. 6/1 Sheet No. | |
|--|-------|
| Other Names: 2. LOCATION: Address: Beside MCB bank, Daryalal street, V street Survey No. Plot No. 6/1 Sheet No. | |
| 2. LOCATION: Address: Beside MCB bank, Daryalal street, V street Survey No. Plot No. 6/1 Sheet No. | |
| Address: Beside MCB bank, Daryalal street, V street Survey No. Plot No. 6/1 Sheet No. | |
| Address: Beside MCB bank, Daryalal street, V street Survey No. Plot No. 6/1 Sheet No. | - |
| Survey No. Survey No. Sheet No. | /irji |
| | • |
| | |
| Coordinates N-24°51.311 E-67°00.093 | |
| District/City/ Town/ Village: Market Quarter's | |
| 3. OWNERSHIP: Private √ Governme | nt |
| Name of Owner (s) PRIVATE | |
| Igbal | |
| 4. OCCUPANCY: Commercial & Residential | |
| 5. REASONS FOR PROTECTION: Architectural Interest: Arches, Pilasters, Cornices & Rosettes | |
| 6. MEASUREMENT: Height- 50' Length- 30' Width- 20' | |
| 7. CONSTRUCTION MATERIAL: Stone Masonry, Charoli | |
| 8 STATUS / PRESENT CONDITION Dilapidated Stable √ Good Condition Needs repa | ir |
| 9. THEREAT(S): Addition & alteration, Encroachment | |
| 10. LOCATION MAP: PHOTOGRAPHS: | |
| DARYA LAL STREET | |
| EIRAISI STREEL RESTREEL RESTRE | |
| IN NOUND TO SERVE IN THE SERVE | |
| 11. COMMENTS: Complete renovated. | cted |
| 11. COMMENTS: Complete renovated. | cted |
| 11. COMMENTS: Complete renovated. The building deserves to be declared as protested. | cted |

58-6/2-MR6



| 1. | IDENTIFICATION: | | G+2 |
|----|----------------------------|---------------------|--------------------|
| | Site Name: | 6/2 | |
| | | | |
| | Other Names: | | |
| 2. | LOCATION: | | |
| | Address: | Virji street Behind | MCB Bank, Daryalal |
| | | Street | • |
| | Survey No. | Plot No. 6/2 | Sheet No. |
| | Coordinates | N-24°51.297 | E-67°00.093 |
| | District/City/ Town/ Villa | age: Market Quarte | r's |
| 3. | OWNERSHIP: | Private √ | Government |
| | Name of Owner (s) | PRIVATE | _ |
| | Mithu Kaka (Kachii) | | |


| 4. | OCCUPANCY: | Commercial & Ro | esidential | · | | | | |
|-----|----------------------------|-----------------|-------------|------------|------------|-----------|-----------|---|
| 5. | REASONS FOR PROTECTION: | Architectural | Interest: E | Balconies, | Pilasters, | Festoon, | Cornice | & |
| | | Decorative Par | apet | | | | | |
| 6. | MEASUREMENT: | Height- 50' | Ler | ngth- | | Width- 50 | , | |
| 7. | CONSTRUCTION MATERIAL: | Stone Masonry | , Charoli | | | | | |
| 8 | STATUS / PRESENT CONDITION | Dilapidated | Stable √ | Good | Condition | Nee | ds repair | |
| 9. | THEREAT(S): | Encroachment | | | | | | |
| 10. | LOCATION MAP: | PHOTOGRAPH | S: | | | | | |





| 11. | COMMENTS: | Well maintained. |
|-----|-----------------------|---|
| 12. | RECOMMENDATIONS | The building deserves to be declared as protected heritage due to its social and architectural value. |
| 13. | NAME OF INVESTIGATOR: | Abdul Fatah |
| 14. | DATE | 22-1- 2018 |


59-ALI HUSAIN, ABDUL HUSAIN BUILDING-MR5




| 1. | IDENTIFICATION: | | |
|----|-------------------------------|-----------------|---------------------|
| | Site Name: | Ali Husain, Abo | dul Husain Building |
| | Other Names: | | |
| 2. | LOCATION: | | |
| | Address: | Off Daryala str | eet |
| | Survey No. | Plot No. 5/10 | Sheet No. |
| | Coordinates | N-24°51.297 | E-67°00.016 |
| | District/City/Town/Village: I | Market Quarter | 's |
| 3. | OWNERSHIP: | Private √ | Government |
| | Name of Owner (s) | PRIVATE | |
| | Haji Muhammad & Haji | | |
| | Hameed | | |

| 4. | OCCUPANCY: | Complete Comm | ercial | | | |
|----|----------------------------|---|------------------------|----------------|--------------|--|
| 5. | REASONS FOR PROTECTION: | Architectural Interest: Arches, Pilasters, Decorative Parapet & | | | | |
| | | Cornices | | | | |
| 6. | MEASUREMENT: | Height- 40' | Length- 35 | , Wid | dth- 20' | |
| 7. | CONSTRUCTION MATERIAL: | Stone Masonr | y, Charoli | | | |
| 8 | STATUS / PRESENT CONDITION | Dilapidated | Stable √ | Good Condition | Needs repair | |
| 9. | THEREAT(S): | Encroachment | t, Addition & Alterati | on on top | | |

10. **LOCATION MAP:**



PHOTOGRAPHS:





| 11. | COMMENTS: | Seems to be in stable condition but also need repair. |
|-----|-----------------------|---|
| 12. | RECOMMENDATIONS | The building deserves to be declared as protected heritage due to its social and architectural value. |
| 13. | NAME OF INVESTIGATOR: | Abdul Fatah |
| 14. | DATE | 26-1- 2018 |

60-BOMBAY HOUSE-MR5

| | | 1. IDENTIFICATION: | G+2 |
|-------------------|--|--|----------|
| | | Site Name: Bombay House | |
| | | Other Names: Green House | |
| | | 2. LOCATION: | |
| | | Address: Near Adam Masjid, Khoosa lane, | , Ali |
| | | Akbar street, Jodia Bazar | |
| | | Survey No. Plot No. 5/45 Sheet No. | |
| | | Coordinates N-24°51.284 E-67°00.023 | 3 |
| | | District/City/ Town/ Village: Market Quarter's | |
| | | 3. OWNERSHIP: Private √ Government | nent |
| | | Name of Owner (s) | |
| | | Wife of Abdul Ghafoor | |
| 4. | OCCUPANCY: | esidential & Commercial | |
| 5. | REASONS FOR PROTECTION: | Architectural Interest: Balconies & decorative parapet | |
| 5. 5. | MEASUREMENT: | Height- 50' Length- 25' Width- 12' | |
| 7. | CONSTRUCTION MATERIAL: | Stone Masonry, Charoli | |
| 8 | STATUS / PRESENT CONDITION | Dilapidated Stable V Good Condition Needs re | pair |
| 9. | THEREAT(S): | Encroachment, Addition & Alteration | <u> </u> |
| 10. | LOCATION MAP: | PHOTOGRAPHS: | |
| | DARYA LAL STREET AND THE STRAIS STREE CONTROL OF THE STRAIS STREET CONTROL OF THE STRAIS STREET CONTROL OF THE STRAIS STREET CONTROL OF THE STREET CONTROL | | |
| 11. | COMMENTS: | Seems to be in stable condition but need to be repaired. | |
| 12. | RECOMMENDATIONS | The building deserves to be declared as pro- heritage due to its social and architectural value. | tecte |
| 13. | NAME OF INVESTIGATOR: | Abdul Fatah | |
| | | The second of th | |


61-HAJI RAZAK JANOD-MR6

| I | | 1. | IDENTIFIC | ATION: | | |
|------------|----------------------------|--------|-------------------------|-----------------|----------------------|--------------------|
| | | | Site Name | | Haji Razak Janod | |
| | | | Other Nar | nes: | Haji Adam Pir Muh | nammad |
| | | 2. | LOCATION | N: | | |
| | | | Address: | | Near I.T Traders, A | bdul Rehman street |
| | | | | | & Feroz street Jod | ia Bazar |
| | | | Survey No |). | Plot No. 6/7 | Sheet No. |
| | | | Coordinat | es | N-24°51.273 | E-67°00.114 |
| | | | District/Ci | ity/ Town/ Vill | age: Market Quarte | er's |
| | THE STATE OF | 3. | OWNERSH | IIP: | Private √ | Government |
| | | | Name of C | wner (s) | | |
| | | | Haji Adam | PIr | | |
| | Many Many | | Muhamma | | | |
| 4. | OCCUPANCY: | | plete Comr | | | |
| 5. | REASONS FOR PROTECTION: | | | | nies, Roundels, Dec | orative parapet |
| | | | | nents & Cornic | | |
| 6. | MEASUREMENT: | _ | ght- 45' | Lengt | n- 40′ | Width- 30' |
| 7. | CONSTRUCTION MATERIAL: | | ne Masonry | | 0 10 1::: | |
| 8 | STATUS / PRESENT CONDITION | _ | | Stable V | Good Condition | Needs repair |
| 9. | THEREAT(S): | | roachment | • | | |
| 10. | LOCATION MAP: | Ph | OTOGRAPH | | | |
| | Location Map | | | | | |
| 11. | Location Map | See | ems to be i | | ndition. Partially r | maintained. |
| 11. 12. | Location Map | Th | e buildin | n a stable co | to be declar | ed as protected |
| 12. | COMMENTS: RECOMMENDATIONS | The | e buildin ritage due | n a stable co | | ed as protected |
| | Location Map COMMENTS: | The he | e buildin | n a stable co | to be declar | ed as protected |


62-ZEESHAN MILL BUILDING-MR7

| | | 1. IDENTIFICATION: Site Name: Other Names: 2. LOCATION: Address: Survey No. Coordinates District/City/ Town/ Ville Other Names: District/City/ Town/ Ville District/City/ Town/ Vill | | Beside Lal Masjid, Qazi Suleman Lane, Bolton Market Plot No. 4/67 Sheet No. N-24°51.210 E-67°00.098 | | |
|-------------------------------------|----------------------------|---|--------------------|---|-------------------------------|--|
| | 3 | | | Private V | Government | |
| | | Name of Askari B | f Owner (s) ank | PRIVATE | | |
| 4. OCCUPANCY: | C | Commercial | | | | |
| 5. REASONS FOR PROTEC | | Architectura | | | | |
| 6. MEASUREMENT: | | Height- 40' | | th- 25' | Width- 20' | |
| 7. CONSTRUCTION MATE | | Stone Mason | | 1 | | |
| 8 STATUS / PRESENT COI | | Dilapidated | Stable V | Good Condition | Needs repair | |
| 9. THEREAT(S): 10. LOCATION MAP: | | Complete Re | | | | |
| Location Map | (PART) ROAD JEEMAN LANE W | as | Raribank A | | | |
| 11. COMMENTS: | C | Completely | renovated by | the Bank. | | |
| 12. RECOMMENDATIONS | | | | s to be declar al and architectu | ed as protected ral value. | |
| 13. NAME OF INVESTIGAT | | _ | | | | |
| 13. NAIVIE OF INVESTIGATE | JR. A | Abdul Fatal | 1 | | | |

63-DEVI MANDIR-MR3




64-BASTAKI MANZIL-MR6




65-RAM PADHOMAL BUILDINHG-MR6

| | | 1. | IDENTIFICATION: | | |
|-----|----------------------------|-----------------|----------------------------|--------------------|--------------------|
| | | | Site Name: | RAM PADHOMAL E | BUILDING |
| | | | Other Names: | | |
| | | 2. | LOCATION: | | |
| | | | Address: | Zakariya Lane, Abd | lul Reham Street, |
| | | | | Opposite Sharifi M | asjid, Jodia Bazar |
| | | | Survey No. | Plot No. 6/17 | Sheet No. |
| | | | Coordinates | N-24°51.260 | E-67°00.110 |
| | | | District/City/ Town/ Villa | age: Market Quarte | r's |
| | | 3. | OWNERSHIP: | Private √ | Government |
| | | | Name of Owner (s) MULTIPLE | PRIVATE | |
| 4. | OCCUPANCY: Co | omm | ercial & Residential but V | acant | |
| 5. | REASONS FOR PROTECTION: | Arc | hitectural Interest: Arc | hes, Pilasters, De | corative Parapet & |
| | | Cor | nices | | |
| 6. | MEASUREMENT: | | | :h- 40' | Width- 40' |
| 7. | CONSTRUCTION MATERIAL: | _ | ne Masonry, Charoli | T | |
| 8 | STATUS / PRESENT CONDITION | _ | apidated Stable V | Good Condition | Needs repair |
| 9. | THEREAT(S): | _ | croachment, Addition & Al | teration on top | |
| 10. | LOCATION MAP: | PHO | OTOGRAPHS: | | |
| | Location Map | | | | |
| 11. | COMMENTS: | Pai | rtially Maintained but s | eems to be in stab | le condition. |
| 12. | | Th | e building deserves | to be declare | ad as protected |
| | RECOMMENDATIONS | 1 111 | c banama accentes | to be acciait | ed as protected |
| | | he | ritage due to its socia | | • |
| 13. | NAME OF INVESTIGATOR: | he Ab | | | • |

66-MUHAMMAD SHAFIQ MASALAI WALA-MR6



67-CHAUDHARY PIRACHA CHAMBERS-MR4




68-GULZAR MANZIL-MR5

| | - An | 1. | IDENTIFICATION: | | |
|-----|---|-------------------------|--|--|--|
| | | | Site Name: | GULZAR MANZIL | |
| | | | | | |
| | | | Other Names: | | |
| | | 2. | LOCATION: | | |
| | | | Address: | Opposite syed Iqra | ar Shah Dargah, Old |
| | | | | Dispensary Road, I | Khooshal lane, |
| | | | | Mithadar Choowk | |
| | | | Survey No. | Plot No. 5/15/2 | Sheet No. |
| | | | Coordinates | N-24°51.282 | E-67°00.014 |
| | | | District/City/ Town/ Vil | lage: Market Quarte | r's |
| | | 3. | OWNERSHIP: | Private √ | Government |
| | | | Name of Owner (s) | PRIVATE | |
| | | | UNKNOWN | | |
| 4. | OCCUPANCY: | Com | mercial & Residential | | |
| 5. | REASONS FOR PROTECTION: | Arc | chitectural Interest: Arche | es, Pilasters & Cornic | |
| 6. | MEASUREMENT: | _ | <u> </u> | th- 40' | Width- 30' |
| 7. | CONSTRUCTION MATERIAL: | | ne Masonry, Charoli | | |
| 8 | STATUS / PRESENT CONDITION | | apidated Stable √ | Good Condition | Needs repair |
| 9. | THEREAT(S): | Two | o floor Addition & Alterat | ion on top, Encroach | ment |
| | | | | | |
| 10. | LOCATION MAP: | | OTOGRAPHS: | | |
| | DARYA LAL STREET ANE E SIRAIS S Location Map | PHO | OTOGRAPHS: | | |
| 11. | DARYA LAL STREET ANE E STRAIS S RANGE | On | OTOGRAPHS: | nd in original condi | ition but rest of the |
| 11. | DARYA LAL STREET TANE SIRAIS S Location Map COMMENTS: | On | OTOGRAPHS: Ily façade is in stable ar ilding is slowly and steal | nd in original condinatily in the process | ition but rest of the sof modernization. |
| | DARYA LAL STREET ANE E SIRAIS S Location Map | On bui | OTOGRAPHS: Ily façade is in stable and ilding is slowly and steaded building deserved. | nd in original condinadily in the process to be declared | ition but rest of the sof modernization. |
| 11. | Location Map COMMENTS: RECOMMENDATIONS | On bui The | otographs: Ily façade is in stable are ilding is slowly and steel e building deserve ritage due to its soci | nd in original condinadily in the process to be declared | ition but rest of the sof modernization. |
| 11. | DARYA LAL STREET TANE SIRAIS S Location Map COMMENTS: | On bui The hei | OTOGRAPHS: Ily façade is in stable and ilding is slowly and steaded building deserved. | nd in original condinadily in the process to be declared | ition but rest of the sof modernization. |

69-SHELHA MANSION-MR5

| | | 1. | IDENTIFICATION: | | | |
|-----|----------------------------|--------------|--|-----------------------|------------------------|--|
| | | | Site Name: | SHELHA MANSION | | |
| | | | Other Names: | | | |
| | | 2. | LOCATION: | | | |
| | | | Address: | Near Sindh bank, d | laryalal street, Jodia | |
| | | | | Bazar | • | |
| | | | Survey No. | Plot No. 5/60 | Sheet No. | |
| | | | Coordinates | N-24°51.305 | E-67°00.042 | |
| | | | District/City/ Town/ Vil | lage: Market Quarte | r's | |
| | | 3. | OWNERSHIP: | Private √ | Government | |
| | | | Name of Owner (s) | PRIVATE | | |
| | | | Mukhtiyar Memon | | | |
| 4. | OCCUPANCY: | | mercial & Residential | | | |
| 5. | REASONS FOR PROTECTION: | Arc | :hitectural Interest: Balo | conies, Pilasters, Co | rnices & Decorative | |
| | | | apet | | | |
| 6. | MEASUREMENT: | | | th- 40' | Width- 25' | |
| 7. | CONSTRUCTION MATERIAL: | | ne Masonry, Charoli | T | | |
| 8 | STATUS / PRESENT CONDITION | _ | apidated Stable V | Good Condition | Needs repair | |
| 9. | THEREAT(S): | Encroachment | | | | |
| | | _ | | | | |
| 10. | LOCATION MAP: | _ | OTOGRAPHS: | | | |
| 10. | | _ | | | | |
| 11. | LOCATION MAP: | PH | | seems to be in stab | le condition. | |
| | LOCATION MAP: | PH | OTOGRAPHS: | | | |
| 11. | LOCATION MAP: A | PH PH | OTOGRAPHS: Trially maintained but s | s to be declare | ed as protected | |
| 11. | LOCATION MAP: A | PH Pa | OTOGRAPHS: Private of the second of the sec | s to be declare | ed as protected | |

70-KHADIJA BAI BUILDING-MR1




71-HARIS BHAI BUILDING-MR1

| | The state of the s | 1. | IDENTIFICATION: | | | |
|------------|--|---|--|---------------------------------------|-----------------------|--|
| | THE TAX | | Site Name: | HARIS BHAI BUILDI | NG | |
| | The state of the s | | Other Names: | | | |
| | A CONTRACTOR OF THE PARTY OF TH | 2. | LOCATION: | | | |
| | | | Address: | Beside Muslah-e- U | Jddin Masjid | |
| | - Commission of the Commission | | | Rambharti Road, B | olton Market | |
| | MIT MANNE HELD | | Survey No. | Plot No.1/34 | Sheet No. | |
| | | | Coordinates | N-24°51.251 | E-67°00.165 | |
| | | | District/City/ Town/ Vill | age: Market Quarte | r's | |
| | | 3. | OWNERSHIP: | Private √ | Government | |
| | Proceedings & Comments | | Name of Owner (s) Mohammad Ali | PRIVATE | | |
| 4. | OCCUPANCY: | Com | nmercial & Residential | 1 | | |
| 5. | REASONS FOR PROTECTION: | Arc | chitectural Interest: Balco | nies, Pilasters, Corn | ices, Floral Design & | |
| | | Dec | corative Parapet | | | |
| 6. | MEASUREMENT: | _ | <u> </u> | h- 50′ | Width- 40' | |
| 7. | CONSTRUCTION MATERIAL: | | ne Masonry, Charoli | 1 | | |
| 8 | STATUS / PRESENT CONDITION | | apidated Stable √ | Good Condition | Needs repair | |
| 9. | THEREAT(S): | Addition & Alteration on top two floor Encroachment | | | | |
| | | | • | | | |
| 10. | LOCATION MAP: | PH | OTOGRAPHS: | | | |
| | PARA LANE QVOR ROAD ROAD ROAD ROAD ROAD ROAD | - | OTOGRAPHS: | | | |
| 11. | PARA LANE OPOLI ROAD | - | OTOGRAPHS: | | | |
| | PARA LANE QVOR ROAD ROAD ROAD ROAD ROAD ROAD | Fag Th | OTOGRAPHS: Gade seems to be in stale building deserves | ble condition. Parties to be declared | ially maintained. | |
| 11. | PARA LANE QUE DIA PARA LANE QUE DIA PARA LANE ROAD | Faç Th | OTOGRAPHS: Gade seems to be in stale building deserves ritage due to its soci | ble condition. Parties to be declared | ially maintained. | |
| 11. 12. | DARA LANE ROAD ROAD ROAD ROAD ROAD RECOMMENTS: | Fag Th he Ab | OTOGRAPHS: Gade seems to be in stale building deserves | ble condition. Parties to be declared | ially maintained. | |

72-MENGHRAJ BUILDING-MR1

| | | 1. IDENTIFICATION: |
|--------------|--|--|
| | | Site Name: MENGHRAJ BUILDING |
| | | Other Names: Haji Abdullah Market |
| | NACAGE | 2. LOCATION: |
| | | Address: Ram Bharti street, Beside Badri Masjid, Marriot Road |
| | | Survey No. Plot No. 1/39 Sheet No. |
| | | Coordinates N-24°51.180 E-67°00.197 |
| | | District/City/ Town/ Village: Market Quarter's |
| | Control of the second of the s | 3. OWNERSHIP: Private √ Government |
| | | Name of Owner (s) PRIVATE |
| 4. | OCCUPANCY: | Ayaz Nadeem Commercial & Residential |
| 5. | REASONS FOR PROTECTION: | Architectural Interest: Arches, Cornices, Balconies & Pilasters |
| 6. | MEASUREMENT: | Height- 50' Length- 50' Width- 35' |
| 7. | CONSTRUCTION MATERIAL: | Stone Masonry, Charoli |
| 8 | STATUS / PRESENT CONDITION | Dilapidated Stable V Good Condition Needs repair |
| 9. | THEREAT(S): | Addition & Alteration |
| 10. | LOCATION MAP: | PHOTOGRAPHS: |
| | ROAD WHORI ROAD WHORI ROAD international bottom account of the second o |
| 11. | COMMENTS: | Partially maintained. |
| 12. | RECOMMENDATION | The building deserves to be declared as protected |
| | | heritage due to its social and architectural value. |
| 13. | NAME OF INVESTIGATOR: | Abdul Fatah |
| 14. | DATE | 11-1- 2018 |
| 4 -7. | DAIL | 111 2010 |

73-JAMAL MANSION-MR1




74-MANDVI WALA-MR1



| 1. | IDENTIFICATION: | | |
|----|----------------------------|----------------------|----------------------|
| | Site Name: | MANDVI WALA | |
| | | | |
| | Other Names: | | |
| 2. | LOCATION: | | |
| | Address: | Ram Bharti street, E | Beside Badri Masjid, |
| | | Marriot Road | |
| | Survey No. | Plot No. 1/41 | Sheet No. |
| | Coordinates | N-24°51.187 | E-67°00.208 |
| | District/City/ Town/ Villa | age: Market Quarter | 's |
| 3. | OWNERSHIP: | Private √ | Government |
| | Name of Owner (s) | PRIVATE | |
| | Haji Shaqoor Memon | | |
| | | | |

| 4. | OCCUPANCY: | Complete Comm | nercial | · | | | | |
|----|----------------------------|---------------|------------|------------|-----------|------------|------------|---|
| 5. | REASONS FOR PROTECTION: | Architectural | Interest: | Roundels, | Arches, | Pilasters, | Cornices | & |
| | | Decorative Pa | rapet | | | | | |
| 6. | MEASUREMENT: | Height- 60' | l | ength- 50' | | Width | n- 40' | |
| 7. | CONSTRUCTION MATERIAL: | Stone Masonr | y, Charoli | | | | | |
| 8 | STATUS / PRESENT CONDITION | Dilapidated | Stable √ | Good (| Condition | Ne | eds repair | |
| 9. | THEREAT(S): | Encroachmen | t | | | | | |

10. LOCATION MAP:



PHOTOGRAPHS:









| 11. | COMMENTS: | Partially Maintained and seems to be in stable condition. | | | | | | |
|-----|-----------------------|---|--|--|--|--|--|--|
| 12. | RECOMMENDATIONS | The building deserves to be declared as protected | | | | | | |
| | | heritage due to its social and architectural value. | | | | | | |
| 13. | NAME OF INVESTIGATOR: | Abdul Fatah | | | | | | |
| 14. | DATE | 11-1- 2018 | | | | | | |

75-HAFIZ MUHAMMAD YOUSAF BUILIDNG-MR4

| Site Name: HAFIZ MUHAMMAD YOUSAF BUILDING Other Names: 2. LOCATION: Address: Murad Khan Road, Kucchi Wada No.3 Survey No. Plot No. 4/38 Sheet No. Coordinates N- E- District/City/ Town/ Village: Market Quarter's 3. OWNERSHIP: Private V Government Name of Owner (s) UNKNOWN 4. OCCUPANCY: Commercial 5. REASONS FOR PROTECTION: Architectural Interest: Arches, Pilasters, Balconies, Couple columns, Pediments, Decorative Parapet & Roundels 7. CONSTRUCTION MATERIAL: Stone Masonry, Charoli 8. STATUS / PRESENT CONDITION Dilapidated Stable V Good Condition Needs repair 10. LOCATION MAP: PHOTOGRAPHS: PHOTOGRAPHS: PHOTOGRAPHS: 11. COMMENTS: Partially maintained. The building deserves to be declared as protected heritage due to its social and architectural value. Abdul Fatah 14. DATE | | | 1. | IDENTIFI | CATION: | | |
|--|-----|--|---------|-------------|------------------|--------------------|-----------------------|
| 2. LOCATION: Address: Murad Khan Road, Kucchi Wada No.3 Survey No. Plot No. 4/38 Sheet No. Coordinates N- E- District/City/ Town/ Village: Market Quarter's 3. OWNERSHIP: Private V Government Name of Owner (s) UNKNOWN 4. OCCUPANCY: Commercial Architectural Interest: Arches, Pilasters, Balconies, Couple columns, Pediments, Decorative Parapet & Roundels 6. MEASUREMENT: Height Length Width- CONSTRUCTION MATERIAL: Stone Masonry, Charoli 3. STATUS / PRESENT CONDITION Dilapidated Stable V Good Condition Needs repair 7. LOCATION MAP: PHOTOGRAPHS: PHOTOGRAPHS: PHOTOGRAPHS: 11. COMMENTS: Partially maintained. 12. RECOMMENDATIONS The building deserves to be declared as protected heritage due to its social and architectural value. 13. NAME OF INVESTIGATOR: Abdul Fatah | | | | Site Nam | ne: | HAFIZ MUHAMMA | AD YOUSAF BUILDING |
| Address: Murad Khan Road, Kucchi Wada No.3 Survey No. Plot No. 4/38 Sheet No. Coordinates N- District/City/Town/Village: Market Quarter's 3. OWNERSHIP: Private v Government Name of Owner (s) PRIVATE UNKNOWN 4. OCCUPANCY: Commercial 5. REASONS FOR PROTECTION: Architectural Interest: Arches, Pilasters, Balconies, Couple columns, Pediments, Decorative Parapet & Roundels 6. MEASUREMENT: Height Length Width- CONSTRUCTION MATERIAL: Stone Masonry, Charoli 8 STATUS / PRESENT CONDITION Dilapidated Stable v Good Condition Needs repair 10. LOCATION MAP: PHOTOGRAPHS: PHOTOGRAPHS: PHOTOGRAPHS: 11. COMMENTS: Partially maintained. The building deserves to be declared as protected heritage due to its social and architectural value. 13. NAME OF INVESTIGATOR: Abdul Fatah | | | | Other Na | ames: | | |
| Survey No. Plot No. 4/38 Sheet No. Coordinates N- E- District/City/Town/ Village: Market Quarter's 3. OWNERSHIP: Private \(\frac{1}{2} \) Government Name of Owner (s) UNKNOWN 4. OCCUPANCY: Commercial 5. REASONS FOR PROTECTION: Architectural Interest: Arches, Pilasters, Balconies, Couple columns, Pediments, Decorative Parapet & Roundels 6. MEASUREMENT: Height- Length- Width- 7. CONSTRUCTION MATERIAL: Stone Masonry, Charoli 8 STATUS / PRESENT CONDITION Dilapidated Stable \(\frac{1}{2} \) Good Condition Needs repair 9. THEREAT(S): 10. LOCATION MAP: PHOTOGRAPHS: PHOTOGRAPHS: PHOTOGRAPHS: 11. COMMENTS: Partially maintained. 12. RECOMMENDATIONS Partially maintained. N- Politory Village: Market Quarter's Government of Governmen | | | 2. | LOCATIO | N: | | |
| Coordinates N- E- | | | | Address | | Murad Khan Road | , Kucchi Wada No.3 |
| District/City/Town/Village: Market Quarter's 3. OWNERSHIP: Private \(\) Government Name of Owner (s) UNKNOWN 4. OCCUPANCY: Commercial 5. REASONS FOR PROTECTION: Architectural Interest: Arches, Pilasters, Balconies, Couple columns, Pediments, Decorative Parapet & Roundels 6. MEASUREMENT: Height Length Width 7. CONSTRUCTION MATERIAL: Stone Masonry, Charoli 8 STATUS / PRESENT CONDITION 9. THEREAT(S): 10. LOCATION MAP: PHOTOGRAPHS: PHOTOGRAPHS: PHOTOGRAPHS: 11. COMMENTS: Partially maintained. 12. RECOMMENDATIONS The building deserves to be declared as protected heritage due to its social and architectural value. 13. NAME OF INVESTIGATOR: Abdul Fatah | | | | Survey N | lo. | Plot No. 4/38 | Sheet No. |
| 3. OWNERSHIP: Private V Government Name of Owner (s) PRIVATE VINKNOWN 4. OCCUPANCY: Commercial 5. REASONS FOR PROTECTION: Architectural Interest: Arches, Pilasters, Balconies, Couple columns, Pediments, Decorative Parapet & Roundels 6. MEASUREMENT: Height Length Width- 7. CONSTRUCTION MATERIAL: Stone Masonry, Charoli 8 STATUS / PRESENT CONDITION Dilapidated Stable V Good Condition Needs repair 9. THEREAT(S): 10. LOCATION MAP: PHOTOGRAPHS: PHOTOGRAPHS: 11. COMMENTS: Partially maintained. 12. RECOMMENDATIONS PARTIALLY Maintained. The building deserves to be declared as protected heritage due to its social and architectural value. 13. NAME OF INVESTIGATOR: Abdul Fatah | | 8 5 JAN 10 JAN 1 | | Coordina | ates | N- | E- |
| Name of Owner (s) UNKNOWN 4. OCCUPANCY: Commercial 5. REASONS FOR PROTECTION: Architectural Interest: Arches, Pilasters, Balconies, Couple columns, Pediments, Decorative Parapet & Roundels 6. MEASUREMENT: Height Length Width- 7. CONSTRUCTION MATERIAL: Stone Masonry, Charoli 8. STATUS / PRESENT CONDITION Dilapidated Stable V Good Condition Needs repair 9. THEREAT(S): 10. LOCATION MAP: PHOTOGRAPHS: PHOTOGRAPHS: 11. COMMENTS: Partially maintained. 12. RECOMMENDATIONS The building deserves to be declared as protected heritage due to its social and architectural value. Abdul Fatah | | | | District/ | City/ Town/ Vill | age: Market Quarte | er's |
| UNKNOWN 4. OCCUPANCY: Commercial 5. REASONS FOR PROTECTION: Architectural Interest: Arches, Pilasters, Balconies, Couple columns, Pediments, Decorative Parapet & Roundels 6. MEASUREMENT: Height Length Width 7. CONSTRUCTION MATERIAL: Stone Masonry, Charoli 8. STATUS / PRESENT CONDITION 9. THEREAT(S): 10. LOCATION MAP: PHOTOGRAPHS: PHOTOGRAPHS: 11. COMMENTS: Partially maintained. 12. RECOMMENDATIONS Partially maintained. The building deserves to be declared as protected heritage due to its social and architectural value. Abdul Fatah | | | 3. | OWNERS | HIP: | Private √ | Government |
| 4. OCCUPANCY: 5. REASONS FOR PROTECTION: Architectural Interest: Arches, Pilasters, Balconies, Couple columns, Pediments, Decorative Parapet & Roundels 6. MEASUREMENT: Height-Length-Width- 7. CONSTRUCTION MATERIAL: Stone Masonry, Charoli 8 STATUS / PRESENT CONDITION Dilapidated Stable V Good Condition Needs repair 9. THEREAT(S): 10. LOCATION MAP: PHOTOGRAPHS: PHOTOGRAPHS: 11. COMMENTS: Partially maintained. The building deserves to be declared as protected heritage due to its social and architectural value. 13. NAME OF INVESTIGATOR: Architectural Interest: Arches, Pilasters, Balconies, Couple columns, Pediments, Pedim | | | | | | PRIVATE | |
| S. REASONS FOR PROTECTION: Architectural Interest: Arches, Pilasters, Balconies, Couple columns, Pediments, Decorative Parapet & Roundels 6. MEASUREMENT: CONSTRUCTION MATERIAL: Stone Masonry, Charoli STATUS / PRESENT CONDITION Dilapidated Stable V Good Condition Needs repair THEREAT(S): PHOTOGRAPHS: 10. LOCATION MAP: PHOTOGRAPHS: 11. COMMENTS: Partially maintained. 12. RECOMMENDATIONS The building deserves to be declared as protected heritage due to its social and architectural value. Architectural Interest: Arches, Pilasters, Balconies, Couple columns, Pediments, Decorative Parapet & Roundels Width- Good Condition Needs repair PHOTOGRAPHS: Partially maintained. The building deserves to be declared as protected heritage due to its social and architectural value. | _ | | <u></u> | | /N | | |
| Pediments, Decorative Parapet & Roundels 6. MEASUREMENT: Height- Length- Width- 7. CONSTRUCTION MATERIAL: Stone Masonry, Charoli 8 STATUS / PRESENT CONDITION 9. THEREAT(S): 10. LOCATION MAP: PHOTOGRAPHS: PHOTOGRAPHS: 11. COMMENTS: Partially maintained. 12. RECOMMENDATIONS Pediments, Decorative Parapet & Roundels Height- Length- Width- Stone Masonry, Charoli Stable v Good Condition Needs repair PHOTOGRAPHS: PHOTOGRAPHS: 12. RECOMMENDATIONS The building deserves to be declared as protected heritage due to its social and architectural value. 13. NAME OF INVESTIGATOR: Abdul Fatah | | | | | 1.1 A | Dilasta a Dalas | |
| 6. MEASUREMENT: 7. CONSTRUCTION MATERIAL: 8 STATUS / PRESENT CONDITION 9. THEREAT(S): PHOTOGRAPHS: PLOCATION MAP: PHOTOGRAPHS: 11. COMMENTS: Partially maintained. PARTIALLY maintained. PARTIALLY maintained. PARTIALLY maintained. PARTIALLY maintained. The building deserves to be declared as protected heritage due to its social and architectural value. Abdul Fatah | 5. | REASONS FOR PROTECTION: | | | | | nies, Coupie columns, |
| 7. CONSTRUCTION MATERIAL: 8 STATUS / PRESENT CONDITION 9. THEREAT(S): 10. LOCATION MAP: PHOTOGRAPHS: PHOTOGRAPHS: 11. COMMENTS: Partially maintained. The building deserves to be declared as protected heritage due to its social and architectural value. 13. NAME OF INVESTIGATOR: Abdul Fatah | 6 | MEASUREMENT: | | | • | | 1+h_ |
| 8 STATUS / PRESENT CONDITION 9. THEREAT(S): 10. LOCATION MAP: PHOTOGRAPHS: PHOTOGRAPHS PHOTOGRAPHS PHOTOGRAPHS PHOTOGRAPHS | | | _ | _ | | VVIC | 2011 |
| 9. THEREAT(S): 10. LOCATION MAP: PHOTOGRAPHS: Location Map PHOTOGRAPHS: 11. COMMENTS: Partially maintained. The building deserves to be declared as protected heritage due to its social and architectural value. Abdul Fatah | | | _ | | - | Good Condition | Needs repair |
| 11. COMMENTS: Partially maintained. The building deserves to be declared as protected heritage due to its social and architectural value. Abdul Fatah | | | | | | | |
| 11. COMMENTS: Partially maintained. The building deserves to be declared as protected heritage due to its social and architectural value. Abdul Fatah | 10. | LOCATION MAP: | PH | OTOGRAPI | HS: | | |
| 12. RECOMMENDATIONS The building deserves to be declared as protected heritage due to its social and architectural value. 13. NAME OF INVESTIGATOR: Abdul Fatah | | Location Map | | | | | |
| heritage due to its social and architectural value. 13. NAME OF INVESTIGATOR: Abdul Fatah | 11. | COMMENTS: | Pai | rtially mai | ntained. | | |
| 13. NAME OF INVESTIGATOR: Abdul Fatah | 12. | RECOMMENDATIONS | Th | e buildi | ng deserves | to be declar | ed as protected |
| | | | he | ritage du | e to its soci | al and architect | ural value. |
| 14. DATE 12-12-2017 | 13. | NAME OF INVESTIGATOR: | | | | | |
| | 14. | DATE | 12- | 12- 2017 | | | |

76-ZUBAIR MANZIL-MR1

